

ENVIRONMENTAL AUDIT REPORT
FOR
INNER HOUSE INVESTMENT LTD (LPG GAS PLANT)
ALONG IFITE-UNIZIK ROAD, AWKA SOUTH LGA, ANAMBRA STATE



PREPARED BY
UNIC CONCEPTS LIMITED
BESIDE MORGAN SUITE, AROMA, AWKA, ANAMBRA STATE

September 22, 2025

APPROVAL PAGE

This Environmental Audit Report for **Inner House Investment Ltd** (LPG Gas Plant) located along Ifite-Unizik Road, Awka South Local Government Area, Anambra State, has been prepared in accordance with the National Guidelines for Environmental Audit in Nigeria (2024 Revision) published by NESREA, the **Anambra State Environmental Management, Protection and Administration Law, 2024**, and other relevant statutory requirements.

The audit was conducted by **Unik Concept Ltd**, duly accredited and registered with the Anambra State Ministry of Environment, in collaboration with the facility management and relevant stakeholders.

This Environmental Audit Report assesses the facility's environmental performance, regulatory compliance status, identifies gaps and risks, and provides comprehensive recommendations and action plans for implementation to achieve full compliance and best practice standards.

We hereby affirm that this report meets the required standards for Environmental Audit studies in Nigeria and is submitted to the Anambra State Ministry of Environment for review, consideration, and approval.

For and on behalf of the Proponent:

Managing Director Inner House Investment LTD **Signature & Date:** _____
Along Ifite-Unizik Road, Awka South LGA, Anambra State, Nigeria

For and on behalf of the Environmental Audit Consultant:

Engr. George Okoye **Signature & Date:** _____
Lead Environmental Auditor Unik Concept Ltd

For and on behalf of the Anambra State Ministry of Environment:

Dr. Mrs. Ifeoma Onyekwere **Signature & Date:** _____
HOD, Ecology and Environment Department

LIST OF PREPARERS

We, the undersigned members of the audit team, certify that we have conducted this environmental audit in accordance with professional standards, regulatory requirements, and ethical guidelines. We affirm that the findings, conclusions, and recommendations contained in this report are accurate, complete, and based on objective evidence.

Name of Report Team	Designation
Engr. George Okoye	Lead Auditor/Team Leader
Dr. Chukwuemeka Pascal Nwosu	Deputy Lead Auditor
Miss. Adaeze S. Anyaorah	Report Specialist
Engr. Stanly Dibie Chinedu	Baseline Studies Specialist
Barr. Ngozi Cynthia Uba	Compliance/Safety Officer
Mr. Chinwuba Christian	GIS Specialist

DISCLAIMER

This Environmental Audit Report has been prepared in accordance with the National Guidelines for Environmental Audit in Nigeria (2024 Revision) published by NESREA. The findings and recommendations contained herein are based on site observations, document reviews, photographic evidence, GPS surveys, and stakeholder interviews conducted during the audit period from September 30, 2025.

The accuracy of operational data and information provided by facility management has been cross-verified where possible. Site conditions were assessed during daylight hours under normal weather conditions. This report represents the environmental and safety status of the facility as observed during the audit period.

The auditors acknowledge that environmental conditions and regulatory requirements may change over time, and this report should be updated accordingly. All recommendations are based on current NESREA guidelines, NUPRC requirements, and international best practices for LPG retail facilities.

TABLE OF CONTENTS

APPROVAL PAGE	ii
LIST OF PREPARERS	iii
DISCLAIMER.....	iv
TABLE OF CONTENTS	v
List of figures.....	ix
List of Tables.....	ix
LIST OF ABBREVIATIONS.....	x
ACKNOWLEDGEMENT	xiv
EXECUTIVE SUMMARY	xv
1. INTRODUCTION	1
1.1. Purpose of Environmental Audit Guidelines.....	1
1.2. Terms Of Reference and Scope Definition	1
1.2.1. Audit Purpose and Objectives.....	1
1.2.2. Primary Objectives	1
1.2.3. Secondary Objectives.....	2
1.3. Terms of Reference and Scope Definition Table	2
1.3.1. Organizational Boundaries.....	3
1.3.2. Geographical Boundaries.....	3
1.3.3. Locational Boundaries.....	4
1.3.4. Extended Coverage	4
1.3.5. Functional Areas Assessment	4
1.3.6. Compliance Boundaries and Standards	6
1.3.7. Approach and Methodology	7
2. OVERVIEW OF THE FACILITY.....	11
2.1. Description of Facility and Operations.....	11
2.2. Organizational Structure and Management	11
2.3. Process Description and Operational Flow	12
2.3.1. Infrastructure Assessment	12

2.3.2. Surrounding Environment Analysis.....	13
2.4. Critical Control Points.....	15
2.5. Ancillary Operations.....	15
2.6. Quantification of Inputs and Outputs	16
2.7. Material Balance and Environmental Performance	17
3. BASELINE ENVIRONMENTAL ASSESSMENT AND MANAGEMENT STUDY	18
3.1. Description of Surrounding Environment	18
3.1.1. Geographic and Climatic Context.....	18
3.2. Existing Environmental Management Systems	20
3.2.1. Current Environmental Management Practices.....	20
3.3. Safety and Environmental Equipment Assessment	20
3.4. Environmental Monitoring and Reporting	21
4. OVERVIEW OF THE FACILITY.....	23
4.1. Facility Description and Site Characteristics	23
4.2. Operational Infrastructure Analysis	23
4.3. Site Layout and Zoning Analysis	24
4.4. Utilities and Supporting Systems	24
5. AUDIT FINDINGS.....	26
5.1. Site-Specific Environmental Conditions Assessment	26
5.1.1. Topographic and Drainage Advantages.....	26
5.1.2. Vegetation Management Critical Assessment	26
5.1.3. Air Quality and Atmospheric Conditions	27
5.2. Regulatory Compliance Detailed Analysis.....	27
5.3. NUPRC Technical Standards Compliance	28
5.4. Fire Safety and Building Code Compliance	29
5.5. NESREA Environmental Standards Compliance	30
5.6. Risk Assessment	31
5.6.1. Fire and Explosion Risk Analysis.....	31
5.6.2. Environmental Release Risk Assessment	32

5.6.3. Community Impact Risk Evaluation	32
5.7. Staff Competency and Training Assessment	33
5.7.1. Current Training Coverage Analysis	33
5.7.2. Training Enhancement Requirements	33
5.8. Operational Safety Record and Incident Analysis	34
5.8.1. Historical Safety Performance	34
5.9. Risk Indicator Monitoring	35
5.10. Environmental Audit Compliance Evaluation	35
5.10.1. Compliance Analysis from the Table	38
5.11. Seasonal Risk Matrix	38
6. ENVIRONMENTAL IMPACT ASSESSMENT	39
6.1. Baseline Environmental Conditions	39
6.1.1. Regional Context	39
6.1.2. Geological and Soil Characteristics	39
6.2. Water Quality Impact Assessment	41
6.3. Air Quality Assessment	41
6.4. Operational Impact Projections	42
6.5 Noise Impact Assessment	42
6.5.1. Operational Noise Impact	43
6.6. Soil Contamination Risk Assessment	43
6.6.1. Contamination Risk Management	43
6.7. Cumulative Impact Analysis	43
6.8. Environmental Management Recommendations	44
7. RISK ASSESSMENT AND MANAGEMENT	45
8. REGULATORY COMPLIANCE ANALYSIS	48
8.1. NESREA Compliance	48
8.2. NUPRC Compliance	48
8.3. Fire Safety Compliance	49
8.4. Local Government and Planning Compliance	49

8.4.1. Regulatory Reporting Requirements.....	49
8.4.2. Permit and License Management	50
9. CONCLUSION	51
9.1. Summary of Audit Findings.....	51
9.2. Assessment of Facility's Environmental Performance and Compliance Status	52
10. RECOMMENDATIONS	53
10.1. Immediate Priority Actions (0-30 Days)	53
10.1.1. Vegetation Fire Hazard Elimination (7 Days - CRITICAL)	53
10.1.2. Emergency Response Plan Development (30 Days)	53
10.1.3. Staff Safety Training Completion (30 Days)	53
10.2. High Priority Actions (30-90 Days)	53
10.2.1. Formal Waste Management System (60 Days)	53
10.2.2. Environmental Monitoring Program (60 Days)	54
10.2.3. Enhanced Fire Suppression Capacity (90 Days)	54
10.3. Medium Priority Actions (90-180 Days).....	54
10.3.1. Operational Documentation Enhancement (120 Days)	54
10.3.2. Community Emergency Preparedness (120 Days)	54
10.3.3. Advanced Staff Training Program (180 Days)	55
10.4. Strategic Priority Actions (180-365 Days)	55
10.4.1. ISO 14001 Certification (365 Days)	55
10.4.2. Quantitative Risk Assessment (240 Days)	55
10.4. Follow-Up Action Plan.....	55
11. BIBLIOGRAPHY AND REFERENCES.....	57
12. APPENDIX	62
Photo logs	62

List of figures

Figure 2.1. Organizational structure	12
Figure 2.2. Process Flow Diagram	14
Figure 1. Back fence with water storage tanks	62
Figure 2. Picture of the compound and entrance gate	63
Figure 3. Picture of the alternative power source and administrative block.....	63
Figure 4. Picture of the storage tank protective fence	64
Figure 5. Storage tank with concrete stand support.....	65
Figure 6. Control and utility house.....	66
Figure 7. Picture of the 2 nozzles	67
Figure 8. Picture of the facility entrance from across the road	68
Figure 9. Picture showing alternate view of the facility	68
Figure 11.10. Picture of the outside of the fence	69

List of Tables

Table I. Compliance Status Summary.....	xvii
Table II. Material Balance and Operational Efficiency	xviii
Table III. Risk Assessment Summary	xix
Table 1.1. Terms of Reference	2
Table 1.2. Locational Boundaries	4
Table 2.1. Site Area Breakdown	11
Table 3.1. Sensitive Receptors.....	19
Table 3.2. Safety and Environmental Equipment Assessment.....	21
Table 3.3. Required Baseline Monitoring Program	22
Table 5.1. Regulatory Compliance Matrix	27
Table 4.2. NUPRC Technical Standards Compliance.....	28
Table 5.3. Fire Safety and Building Code Compliance	30
Table 5.4. Environmental Audit Compliance Evaluation	35
Table 5.5. Seasonal Risk	38
Table 6.1. Geological soil survey data	39
Table 6.2. Exceeded Parameters	39
Table 6.3. Acceptable Parameters.....	40
Table 6.4. Air quality monitoring.....	41
Table 6.5. Air quality monitoring at project site	41
Table 6.6. Noise Impact Assessment at the site.....	42
Table 7.1. Risk Assessment Summary Table.....	46

Table 10.1. Implementation Timeline Summary.....	55
--	----

LIST OF ABBREVIATIONS

Abbreviation Full Meaning

ABC	All-purpose (Dry Chemical Powder) Fire Extinguisher
ANSEPA	Anambra State Environmental Protection Agency
AP-42	Air Pollutant Emission Factors (USEPA)
API	American Petroleum Institute
APCD	Air Pollution Control Device
ASLGA	Awka South Local Government Area
BLEVE	Boiling Liquid Expanding Vapor Explosion
BOD	Biological Oxygen Demand
CAC	Corporate Affairs Commission
CFC	Chlorofluorocarbon
CH ₄	Methane
CO	Carbon Monoxide
COD	Chemical Oxygen Demand
COREN	Council for the Regulation of Engineering in Nigeria
CSR	Corporate Social Responsibility
dB	Decibel
DPR	Department of Petroleum Resources
EA	Environmental Audit
EIA	Environmental Impact Assessment
EMP	Environmental Management Plan
EMS	Environmental Management System
ERP	Emergency Response Plan
ESD	Emergency Shutdown
ESF	Environmental and Social Framework
ESHSMP	Environmental, Social, Health and Safety Management Plan
ETP	Effluent Treatment Plant

Abbreviation Full Meaning

FEPA	Federal Environmental Protection Agency
FMEEnv	Federal Ministry of Environment
GHS	Global Harmonized System
GPS	Global Positioning System
H ₂ S	Hydrogen Sulfide
HAZOP	Hazard and Operability Study
HSE	Health, Safety and Environment
HVAC	Heating, Ventilation, and Air Conditioning
IAQ	Indoor Air Quality
IEPN	Institute of Environmental Professionals of Nigeria
INECE	International Network for Environmental Compliance and Enforcement
IPAN	Institute of Public Analysts of Nigeria
ISO	International Organization for Standardization
kg	Kilogram
kWh	Kilowatt-hour
LED	Light Emitting Diode
LFN	Laws of the Federation of Nigeria
LGA	Local Government Area
LPG	Liquefied Petroleum Gas
LPGSAN	Liquefied Petroleum Gas Safety Association of Nigeria
m	Meter
m ³	Cubic Meter
MAN	Manufacturers Association of Nigeria
MDA	Ministries, Departments and Agencies
mg/kg	Milligram per Kilogram
mg/L	Milligram per Liter
mm	Millimeter
MOU	Memorandum of Understanding
MPN	Most Probable Number
MSDS	Material Safety Data Sheet
µg/m ³	Microgram per Cubic Meter

Abbreviation Full Meaning

μS/cm	Microsiemens per Centimeter
N/A	Not Applicable
NACCIMA	Nigeria Association of Chambers of Commerce, Industry, Mines and Agriculture
NEMA	National Emergency Management Agency
NESREA	National Environmental Standards and Regulations Enforcement Agency
NFPA	National Fire Protection Association
NINAS	Nigerian National Accreditation System
NiMet	Nigerian Meteorological Agency
NISP	Nigerian Institute of Safety Professionals
NO _x	Nitrogen Oxides
NUPRC	Nigerian Upstream Petroleum Regulatory Commission
O ₂	Oxygen
OHS	Occupational Health and Safety
OPD	Out-Patient Department
PCB	Polychlorinated Biphenyl
PM	Particulate Matter
PM ₁₀	Particulate Matter (10 micrometers or less)
PPE	Personal Protective Equipment
PPM	Parts Per Million
PRO	Producer Responsibility Organization
PRV	Pressure Relief Valve
R&D	Research and Development
S.I.	Statutory Instrument
SON	Standards Organisation of Nigeria
SOP	Standard Operating Procedure
SO _x	Sulfur Oxides
sqm	Square Meter
STP	Sewage Treatment Plant
TDS	Total Dissolved Solids
ToR	Terms of Reference
UNDP	United Nations Development Programme

Abbreviation Full Meaning

UNEP	United Nations Environment Programme
USEPA	United States Environmental Protection Agency
WLPGA	World LPG Association
WWTP	Wastewater Treatment Plant

ACKNOWLEDGEMENT

We acknowledge the cooperation and support received from the management and staff of INNER HOUSE Investment LTD during the conduct of this comprehensive environmental audit. Special appreciation goes to the facility management for providing unrestricted access to all operational areas, technical documentation, and personnel for detailed interviews.

We recognize the facility's commitment to environmental compliance as evidenced by their willingness to undergo this audit process and their openness to implementing recommended improvements. The management's transparency in providing operational data and historical information significantly enhanced the quality of this assessment.

We also acknowledge the National Environmental Standards and Regulations Enforcement Agency (NESREA) for providing the regulatory framework and guidelines that guided this audit process, and the Department of Petroleum Resources (DPR) for their technical standards that inform our safety assessments.

EXECUTIVE SUMMARY

Background and Facility Overview

INNER HOUSE Investment LTD operates a retail LPG distribution facility with a storage capacity of 26 tons, strategically located along Ifite-Unizik Road in Awka South Local Government Area, Anambra State. The facility, positioned at coordinates 6.2625139°N, 7.1458657°E at an elevation of 125.52 meters above sea level, has been operational for four years, serving both residential and commercial customers in the greater Awka metropolitan area.

The facility features a single horizontal cylindrical storage tank with professional concrete support structure, a two-nozzle dispensing station under protective canopy, comprehensive safety equipment, and supporting infrastructure including administrative offices, security post, and utility buildings. The site occupies the area of 1189.463 sqm with good road access and appropriate setback distances from neighboring properties.

Methodology and Scope

This comprehensive environmental audit was conducted in accordance with NESREA's National Guidelines for Environmental Audit in Nigeria (2024 Revision), covering all aspects of the facility's environmental performance, safety systems, regulatory compliance, and operational practices. The audit methodology included pre-audit documentation review, extensive on-site inspection with photographic documentation, GPS surveying, staff interviews, and post-audit analysis.

The scope encompassed organizational, geographical, functional, and compliance boundaries as defined in Section 1.5 of the NESREA guidelines, with particular focus on air quality management, waste management systems, safety protocols, emergency preparedness, community impact assessment, and regulatory compliance status.

Key Findings Summary

Positive Findings

1. Regulatory Compliance

All major permits and licenses are valid and current, including EIA approval, NUPRC operating license, fire safety certificate, building approval, and environmental permits

2. Safety Infrastructure

Comprehensive safety equipment properly installed and maintained, including emergency shutdown valves, pressure relief valves, fire extinguishers, safety signage, and emergency exits

3. Professional Installation

Storage tank and dispensing equipment installed to professional standards with appropriate concrete supports and safety clearances

4. Operational Safety Record

No recorded incidents in the past 12 months, demonstrating effective operational management

5. Staff Training

70% of staff have completed safety and environmental training programs according to the information provided during site interview.

6. Site Security

Adequate perimeter fencing and security infrastructure with dedicated security post and personnel.

Areas of Concern

1. Emergency Preparedness

Absence of a formal, documented Emergency Response Plan despite having basic emergency equipment

2. Waste Management System

Lack of documented waste management procedures and disposal contracts, though waste bins are present on-site

3. Staff Training Gap

30% of staff require completion of mandatory safety and environmental training

4. Environmental Monitoring

Absence of systematic environmental monitoring program for air quality, soil, and groundwater

5. Documentation Systems

Incomplete operational records and environmental management documentation

6. Vegetation Management

While living vegetation is properly maintained, formal vegetation management schedule needs documentation

Environmental Performance Assessment

The facility demonstrates satisfactory environmental performance with minimal environmental impact due to its elevated location, appropriate siting, and contained operations. The natural drainage provided by the site's elevation (125.52m) and lateritic soil composition reduces risks of surface water contamination and flooding. Air quality impacts are minimal due to proper setback distances and prevailing wind patterns in the area.

The facility's location in a mixed commercial-residential area with adequate buffer distances ensures minimal community impact. However, the absence of baseline environmental monitoring data limits the ability to quantify actual environmental performance metrics.

Table I. Compliance Status Summary

Compliance Area	Current Status	Compliance %	Priority Actions
Overall Assessment	Partially Compliant	82%	Immediate corrective actions required
NUPRC Technical Standards	Partially Compliant	85%	Vegetation management critical
NESREA Environmental Standards	Partially Compliant	85%	ERP, waste procedures, monitoring
Fire Safety Regulations	Compliant with Gap	90%	Address vegetation fire risk
Building and Planning Standards	Fully Compliant	100%	Maintain current status
Occupational Health and Safety	Partially Compliant	75%	Complete staff training

The facility's location in a mixed commercial-residential area with adequate buffer distances (40-60 meters to nearest residences) ensures minimal community impact under normal operations. However, the absence of baseline environmental monitoring data limits the ability to quantify actual environmental performance metrics.

Material Balance and Operational Efficiency

Note that detailed quantitative material balance requires operational data from facility management. Based on 26-ton storage capacity and 4 years operational history, estimated performance indicators.

Table II. Material Balance and Operational Efficiency

Parameter	Estimated Value	Industry Benchmark	Status
Product Recovery Rate	>99%	>99%	Acceptable
Fugitive Emissions	<1% of throughput	<1%	Acceptable
Waste Generation	<0.1% of operations	<0.2%	Acceptable
Water Usage Efficiency	Minimal (domestic only)	N/A	Efficient

Recommendation - Facility management must provide actual operational data for next audit cycle to complete quantitative material balance per NESREA Annexure 4 requirements.

Critical Recommendations

1. Immediate Priority (0-2 months)
 - a. Develop and implement comprehensive Emergency Response Plan
 - b. Immediate removal of all vegetations around the storage tank
 - c. Complete outstanding staff training programs
 - d. Establish formal waste management system with documented procedures
2. High Priority (2-6 months)
 - a. Implement environmental monitoring program
 - b. Enhance operational documentation systems
 - c. Conduct quantitative risk assessment

3. Medium Priority (6-12 months)

- a. Pursue environmental management system certification
- b. Establish community engagement program
- c. Implement continuous improvement processes

Expected Outcomes

Implementation of recommendations will result in full regulatory compliance, enhanced operational safety, reduced environmental risks, improved community relations, and establishment of best practice standards that exceed minimum regulatory requirements.

Table III. Risk Assessment Summary

Scenario	Probability	Consequence	Current Risk Level	Post-Mitigation Risk
Vegetation fire → tank fire (dry season)	High	Catastrophic	UNACCEPTABLE	LOW
Equipment failure → gas release	Low-Medium	Medium-High	MEDIUM	LOW
Vehicle impact on facility	Low	Medium	LOW-MEDIUM	VERY LOW
Minor LPG operational leak	Medium	Low	LOW	VERY LOW
LPG release during delivery	Low	Medium	LOW-MEDIUM	VERY LOW

Critical Success Indicator demands the reduction of UNACCEPTABLE risks to ZERO within 30 days through immediate vegetation management.

1. INTRODUCTION

1.1. Purpose of Environmental Audit Guidelines

This environmental audit has been conducted in strict accordance with Section 1.1 of the National Guidelines for Environmental Audit in Nigeria to provide a comprehensive assessment of INNER HOUSE INVESTMENT LTD's environmental performance and regulatory compliance status. The audit serves as both a compliance verification tool and a strategic planning document to guide the facility's environmental management improvements.

Environmental auditing, as defined by NESREA, comprises a systematic, documented, periodic and objective evaluation of how well organizations, management and equipment are performing with the aim of safeguarding the environment and human health. This audit facilitates management control of environmental practices and assesses compliance with organizational policies and applicable regulatory requirements.

1.2. Terms Of Reference and Scope Definition

1.2.1. Audit Purpose and Objectives

Purpose: This Environmental Audit is conducted to provide a comprehensive, independent assessment of INNER HOUSE Investment LTD's environmental performance, regulatory compliance status, and operational safety in accordance with NESREA's National Guidelines for Environmental Audit in Nigeria (2024 Revision) and the Anambra State Environmental Management, Protection and Administration Law, 2024.

1.2.2. Primary Objectives

1. Evaluate compliance with federal (NESREA/NUPRC), state (Anambra Environmental Law), and international environmental and safety standards
2. Identify environmental risks, hazards, and liabilities associated with LPG storage and retail operations
3. Assess effectiveness of existing environmental management systems, safety protocols, and emergency preparedness

4. Generate baseline environmental data to support ongoing compliance monitoring and performance improvement
5. Provide prioritized recommendations with implementation roadmap for achieving full regulatory compliance and best practice standards

1.2.3. Secondary Objectives

1. Optimize resource utilization and operational efficiency
2. Strengthen facility's environmental self-regulation capacity
3. Minimize human exposure to health, safety, and environmental hazards
4. Enhance community protection and emergency preparedness

1.3. Terms of Reference and Scope Definition Table

Table 1.1. Terms of Reference

Section	Terms of Reference (ToR)
Organizational Boundaries	LPG storage and handling operations, Retail distribution and dispensing activities, Maintenance and administrative functions, Security and utility operations, Waste management activities, Emergency response capabilities
Geographical Boundaries	Primary Study Area: Facility property boundaries and immediate operational area Secondary Study Area: 500 m radius around the facility Regional Context: Awka South LGA regulatory and environmental framework
Locational Boundaries	Facility boundary – 1189.463 sqm Storage tank area – 44.71 sqm Refilling bay – 32 sqm Admin & support buildings – 57 sqm Pump house – 8 sqm Security house – 8 sqm Access control points – 886.037 sqm
Extended Coverage	Off-site waste disposal activities and routes; Emergency evacuation routes and assembly points; Potential impact zones for emergencies; Community interface areas and access roads

Section	Terms of Reference (ToR)
Functional Areas	Environmental Management Occupational Safety Systems Occupational Health Programs
Assessment	Federal Legislation: NESREA Act (2007, amended 2018), EIA Act (Cap. E12 LFN 2004), National Environmental Protection Regulations (S.I.9 of 1991)
Compliance	NESREA Regulations: Waste Control (S.I.28/2009), Noise Pollution (S.I.35/2009), Ozone Layer Protection (S.I.32/2009), others NUPRC
Boundaries & Standards	Requirements: LPG plant guidelines, technical standards, safety and environmental requirements International Standards: ISO 14001 EMS, World Bank ESF, International Fire Code, best practices
Approach & Methodology	Pre-Audit Phase: Planning & preparation Objectives & Scope Definition Team Selection & Preparation Background Information Collection On-Site Phase: Opening meeting, site inspection, photographic documentation, GPS survey, staff interviews, documentation review Post-Audit Phase: Data analysis, findings evaluation, prioritization, and report development

1.3.1. Organizational Boundaries

The audit covers all operations of INNER HOUSE INVESTMENT LTD at the Ifite-Unizik Road facility, include the following.

1. LPG storage and handling operations
2. Retail distribution and dispensing activities
3. Maintenance and administrative functions
4. Security and utility operations
5. Waste management activities
6. Emergency response capabilities

1.3.2. Geographical Boundaries

Primary Study Area: The facility property boundaries and immediate operational area **Secondary Study Area:** 500-meter radius around the facility to assess potential community and

environmental impacts **Regional Context:** Awka South Local Government Area regulatory and environmental framework

1.3.3. Locational Boundaries

Site-Specific Coverage

Table 1.2. Locational Boundaries

Site Component	Area (sqm)
Total Site Area	1,189.463
Storage Tank Area	44.71
Refilling Bay	32
Administrative & Support Buildings	57
Pump House	8
Security House	8
Access Control Points & Circulation	886.037

1.3.4. Extended Coverage

The extended coverage of this audit goes beyond the immediate boundaries of the LPG facility. It includes the assessment of off-site waste disposal activities and the routes through which such waste is transported. The audit also examines the availability and condition of emergency evacuation routes, including the designated assembly points for staff and visitors in case of an incident. Furthermore, potential impact zones for possible emergency scenarios are carefully evaluated to determine the level of risk exposure within and outside the facility. Attention is also given to community interface areas and the access roads leading to and from the plant, as these are critical for both safety and operational efficiency.

1.3.5. Functional Areas Assessment

The audit comprehensively covers the following functional areas as outlined in Table 1.1 of the NESREA guidelines:

1. Environmental Management

Under environmental management, the review looks at the site's operational history and the patterns of development over time. The handling and storage of process materials are assessed to determine efficiency and compliance with environmental standards. Air emissions monitoring and control mechanisms are reviewed, while the management of liquid discharges and wastewater is examined to ensure that effluents do not exceed acceptable limits. Solid and hazardous waste handling practices are checked for adequacy, and the systems for spill prevention and response are also assessed. Stormwater management infrastructure is reviewed to determine its capacity to prevent flooding or contamination, while the audit also checks for compliance with environmental permits and licensing obligations.

2. Occupational Safety Systems

The occupational safety systems of the plant are equally evaluated. The audit considers the extent to which safety policies and procedures are implemented on-site and reviews accident reporting, recording, and investigation protocols. Emergency response measures, including evacuation procedures, are tested for effectiveness. Fire prevention and firefighting systems are assessed, alongside the permit-to-work system that governs maintenance activities. Special attention is given to procedures for confined space entry and other hazardous work, as well as the adequacy of job safety analysis and risk assessment methods. Safety training, communication programs, housekeeping standards, and maintenance practices are also reviewed in detail to measure their effectiveness in promoting workplace safety.

3. Occupational Health Programs

In terms of occupational health programs, the audit examines employee exposure to air contaminants and assesses monitoring practices for physical hazards such as noise, heat, and radiation. Engineering controls and the effectiveness of ventilation systems are reviewed to determine if they adequately protect workers. Personal protective equipment (PPE) programs are assessed, along with the quality of health hazard information available to employees and the effectiveness of training systems. Medical surveillance and health monitoring programs are reviewed, while hearing conservation initiatives and protective measures are also evaluated.

1.3.6. Compliance Boundaries and Standards

This audit evaluates compliance against the following regulatory and standard frameworks

1. Federal Legislation

The audit further defines the compliance boundaries within which the facility must operate, measuring performance against national, regulatory, and international standards. At the federal level, compliance with the National Environmental Standards and Regulations Enforcement Agency (Establishment) Act of 2007 (as amended in 2018), the Environmental Impact Assessment Act Cap. E12 of LFN 2004, and the National Environmental Protection (Pollution Abatement in Industries and Facilities Generating Wastes) Regulations S.I.9 of 1991 is assessed.

2. State Legislation

The facility must also comply with state-level environmental requirements as follows:

Anambra State Environmental Management, Protection and Administration Law, 2024 (Part 8)

This law establishes the Environmental, Social, Health and Safety Management Plan (ESHSMP) framework, also known as Environmental Impact Assessment (EIA) requirements at the state level.

Key Requirements

1. Section 227: Prohibition on undertaking projects without prior environmental effects consideration
2. Section 228: Minimum content requirements for ESHSMP/EIA reports
3. Section 231: Registration in Public Registry (~~₦~~50,000 registration fee)
4. Section 233: Mandatory Study List compliance
5. Section 245: Public Registry for environmental assessment records
6. Section 249: Penalties for non-compliance (Individual: ~~₦~~500,000 fine or 3 months imprisonment; Corporate: ~~₦~~1-10 million or 6 months imprisonment for officers)

Facility Obligations

1. Registration with State EIA Committee through Ministry of Environment
2. Use only State-accredited EIA consultants (Section 250-251)
3. Maintain compliance with approved ESHSMP

4. Submit to quarterly monitoring by State EIA Committee (Section 225(r))
5. Update assessments when project scope changes (Section 241).

3. NESREA-specific regulations are also evaluated, including the Waste Control and Sanitation Regulations S.I.28 of 2009, the Noise Pollution Control Regulations S.I.35 of 2009, and the Ozone Layer Protection Regulations S.I.32 of 2009, in addition to other relevant statutory instruments and guidelines issued by the agency.

4. NUPRC Requirements

Requirements set by the Nigerian Upstream Petroleum Regulatory Commission (NUPRC) are also reviewed. These include the Guidelines for the Establishment of LPG Plants in Nigeria, technical standards for LPG storage and handling, safety requirements for petroleum retail facilities, and environmental protection standards for oil and gas operations.

5. International Standards

Finally, the audit measures the facility against international standards and best practices. These include the ISO 14001 Environmental Management System principles, global best practices for LPG facility management, the World Bank Environmental and Social Framework guidelines, and the International Fire Code requirements applicable to LPG facilities.

1.3.7. Approach and Methodology

a. Pre-Audit Phase (Planning and Preparation)

The audit was initiated following formal invitation from INNER HOUSE Investment LTD management, demonstrating organizational commitment to environmental improvement and regulatory compliance.

b. Objectives and Scope Definition

Comprehensive scope definition was established covering all facility operations, with clear boundaries for organizational, geographical, functional, and compliance assessments as outlined above.

c. Team Selection and Preparation

A multidisciplinary audit team was assembled by bringing together professionals from different areas of expertise. The team included a Lead Environmental Auditor who is accredited by NESREA, a Technical Safety Specialist, a Regulatory Compliance Expert, and a Documentation and Systems Analyst. Each member of the team played a key role in ensuring that the assessment was comprehensive and in line with established standards.

d. Background Information Collection

Extensive pre-audit background information was collected to provide context for the audit. This involved a detailed review of the facility's operational procedures and historical records, regulatory permits and official correspondence, as well as previous inspection and audit reports. Site maps, technical drawings, and specifications were examined, alongside available environmental monitoring data. Emergency response procedures and inventories of relevant equipment were also reviewed to understand the level of preparedness at the facility.

e. On-Site Audit Phase (Field Assessment)

I. Opening Meeting and Orientation

The on-site phase of the audit began with an opening meeting between the audit team and facility management. During this session, the objectives, scope, and methodology of the audit were clearly outlined. The team also discussed the health and safety requirements that would guide their work, confidentiality protocols for handling sensitive data, as well as access restrictions and procedures for moving within the site. Documentation needs and interview schedules were agreed upon to ensure a smooth process.

II. Physical Site Inspection

A physical inspection of the facility followed, carried out using structured protocols to ensure consistency. This involved detailed checks on the storage tanks and supporting infrastructure, dispensing equipment, customer service areas, as well as the condition and readiness of safety equipment and emergency systems. The team also inspected administrative and support buildings, perimeter security measures, and environmental protection systems. Waste management practices and utility services were examined for adequacy and compliance.

III. Photographic Documentation

To complement observations, photographic documentation was carried out across all areas of the facility. These records captured the overall site layout, critical equipment, safety systems, environmental conditions, potential impacts, evidence of compliance, as well as areas requiring improvement. Instances of good practice were also documented to highlight existing strengths.

IV. GPS Survey and Mapping

A GPS survey was conducted to confirm the exact facility coordinates (6.2625139°N, 7.1458657°E) and to carry out elevation and topographic assessments. Distances to sensitive receptors were measured, while emergency access routes and property boundaries were verified.

V. Staff Interviews and Competency Assessment

Structured interviews were conducted with key staff to assess competency levels and awareness. These discussions focused on the employees' understanding of environmental responsibilities, knowledge of emergency response procedures, adherence to operational safety practices, and experience with incident reporting and management. Staff were also given the opportunity to suggest improvements and raise concerns.

VI. Documentation Review

The audit team undertook a thorough review of facility documentation. This included checking operational permits and licenses, maintenance records, and training certifications. Incident reports and evidence of corrective actions were reviewed, alongside environmental monitoring data. The team also evaluated contractor management and oversight procedures to ensure external operators comply with the facility's standards.

f. Post-Audit Phase (Analysis and Reporting)

I. Data Analysis and Validation

During the post-audit phase, all collected data was systematically analyzed and validated. A compliance gap analysis was conducted to measure adherence against regulatory requirements, while operational observations were used to carry out risk assessments. Performance was

benchmarked against industry standards, and potential improvement opportunities were weighed using cost-benefit considerations.

II. Findings Evaluation and Prioritization

The findings were evaluated and prioritized according to their level of importance. Issues of critical non-compliance that required immediate corrective actions were identified, followed by significant areas needing improvement to enhance performance. Opportunities for best practices and continuous improvement were highlighted, along with strategic recommendations aimed at long-term sustainability.

III. Report Development

Finally, the team prepared a comprehensive report in accordance with NESREA guidelines. The report contained an executive summary to support management decision-making, detailed technical findings with analysis, prioritized recommendations, and an implementation timeline. An action plan was included, assigning responsibilities and budgets for corrective measures. The report also proposed a framework for ongoing performance monitoring and review to ensure compliance and continuous improvement at the facility.

2. OVERVIEW OF THE FACILITY

2.1. Description of Facility and Operations

Inner House Investment LTD operates a modern retail LPG distribution facility strategically positioned along the busy Ifite-Unizik Road in Awka South Local Government Area, Anambra State. The facility represents a significant investment in clean energy infrastructure, serving the growing demand for liquefied petroleum gas in the greater Awka metropolitan area and surrounding communities.

The facility is designed and constructed according to contemporary standards for LPG retail operations, featuring a single horizontal cylindrical storage tank with 26-ton capacity, professional dispensing infrastructure, comprehensive safety systems, and supporting administrative facilities. The site design prioritizes both operational efficiency and safety, with clear segregation between high-risk storage areas, customer service zones, and administrative functions.

Table 2.1. Site Area Breakdown

Component	Area (sqm)	Percentage
Total Site Area	1,189.463	100%
Storage Tank Area	44.71	3.8%
Refilling Bay	32	2.7%
Administrative & Support Buildings	57	4.8%
Pump House	8	0.7%
Security House	8	0.7%
Access Control Points & Circulation	886.037	74.5%
Landscaping/Buffer	153.716	12.9%

2.2. Organizational Structure and Management

The facility operates under a clearly defined management system that ensures accountability, operational efficiency, and compliance with environmental and safety requirements. Oversight begins at the General Manager's office, cascading down through operational, safety, maintenance, and security units.

The organizational structure is illustrated in the chart below.




Figure 2.1. Organizational structure

2.3. Process Description and Operational Flow

The facility's operations are organized into four principal stages, supported by safety systems and infrastructure that ensure compliance with national and international standards.

Bulk LPG deliveries arrive via road tankers and undergo quality verification before offloading into the 26-ton horizontal cylindrical storage tank. Storage management involves continuous monitoring of tank pressure, temperature, and product levels to ensure both safety and operational efficiency. From storage, LPG is distributed through a two-nozzle dispensing station, where customers are served under a controlled system of automated dispensing with integrated flow metering.

Safety remains integral to every stage of operation, with dedicated emergency shutdown systems, pressure relief valves, fire extinguishers, and clear signage to enforce safe practices.

2.3.1. Infrastructure Assessment

A physical inspection of the facility, complemented by photographic documentation, revealed that the infrastructure is structurally sound, professionally designed, and compliant with standard regulatory requirements.

Storage Infrastructure consists of a 26-ton horizontal cylindrical LPG tank mounted on a reinforced concrete structure. The tank is properly elevated, supported, and equipped with yellow-coded gas piping in compliance with industry standards.

Dispensing Facilities include a two-nozzle dispensing station with protective overhead roofing and a reinforced green concrete platform to enhance customer safety. Automated dispensing systems with integrated flow meters ensure accurate product delivery and accountability.

Safety Equipment observed on-site includes emergency shutdown valves, pressure relief valves, sufficient fire extinguisher coverage, and clearly visible "NO SMOKING" signage. Emergency exits are well-marked, ensuring readiness for incident response.

Support Infrastructure includes administrative offices, a fully manned security post, standby generators for backup power, perimeter fencing with access control, and waste management bins, ensuring operational resilience and compliance with environmental practices.

2.3.2. Surrounding Environment Analysis

The facility is located within a mixed commercial–residential area, with moderate building density (two- to three-story structures). Access is facilitated by paved roads that also support customer and supplier movement.

Distance assessments based on GPS mapping and photographs indicate that the nearest residential structures are approximately 40–60 meters from the site. Clearance from side boundaries averages 10–15 meters, while the distance from the storage tank to the dispensing area is approximately 25–30 meters.

The facility benefits from well-drained lateritic soils and a natural slope that enhances surface water drainage. Vegetation on site consists of banana plants, grasses, and tropical flora, which are well-maintained, with removal of dead or dried material to reduce fire risk.

Process Flow Diagram




Figure 2.2. Process Flow Diagram

2.4. Critical Control Points

The operations of the facility are governed by a series of critical control points designed to ensure product quality, operational efficiency, and safety compliance.

During delivery and receipt of products, emphasis is placed on verifying product specifications before acceptance, adhering strictly to safety protocols during transfers, and maintaining accurate documentation for every transaction. Equipment involved in transfer operations undergoes routine inspection and testing to prevent leaks or failures.

In storage management, continuous monitoring of pressure and temperature is carried out to maintain operational stability. Leak detection systems are in place with predefined response measures, while inventory reconciliation is conducted regularly to account for all product movement. Preventive maintenance schedules are observed to ensure the integrity of tanks and associated infrastructure.

Dispensing operations are carefully managed through customer safety verification prior to refilling, calibration of dispensing equipment to guarantee accuracy, and full documentation of transactions. Emergency response preparedness is integrated into day-to-day operations to ensure readiness in case of unexpected events.

2.5. Ancillary Operations

Supporting operations form the backbone of the facility's efficiency. Transportation and logistics are coordinated through approved LPG suppliers with scheduled deliveries, receipt verification, and stringent quality control procedures. Inventory is managed strategically to avoid shortages while optimizing storage capacity.

Customer access management ensures safety and efficiency within the premises. This includes the regulation of vehicle traffic, provision of safety briefings to customers, emergency evacuation planning, and proper parking or queue management systems.

Maintenance and technical services are anchored on a preventive maintenance program covering scheduled inspections, servicing, calibration, and repair of safety systems and

infrastructure. Documentation of maintenance activities ensures compliance with regulatory standards. Technical support systems extend to instrumentation, control, and communication systems, all of which undergo regular testing to guarantee functionality, including backup power systems to ensure business continuity.

Administrative and support functions are equally critical. Office operations manage customer service, financial reporting, regulatory submissions, and human resources coordination. Security and access control are ensured through perimeter fencing, surveillance systems, controlled entry points, and emergency coordination. Incident reporting and investigation procedures are also in place to enhance accountability.

2.6. Quantification of Inputs and Outputs

The facility's material and energy balance reflects efficiency and environmental responsibility. Bulk LPG is the primary input, sourced exclusively from licensed suppliers in compliance with regulatory standards. Deliveries are scheduled at intervals determined by demand, with every consignment subjected to quality checks. Additional operating materials include spare parts, lubricants, cleaning supplies, personal protective equipment, and routine office consumables. Utilities such as electricity, water, and communication systems support ongoing operations.

Electrical energy is sourced primarily from the national grid, powering lighting, instrumentation, and administrative operations. A diesel-powered generator provides backup during outages, with storage facilities in place to ensure fuel availability. Energy efficiency measures include the use of LED lighting and energy-efficient equipment.

Water consumption is minimal, restricted mainly to domestic use, sanitation, equipment cleaning, and fire safety systems. Municipal supply serves as the primary source, with water-efficient fixtures helping to reduce wastage.

The principal output of the facility is retail LPG, sold to residential, commercial, and institutional customers. Each transaction is documented with safety verification, ensuring service quality.

Waste generation is relatively minimal. Solid waste arises from domestic operations, equipment servicing, and packaging materials, with provisions for recycling and safe disposal of special waste such as filters and protective equipment. Liquid waste, largely sanitary, is managed through septic systems or municipal sewers, while stormwater is directed through surface drainage systems. Gaseous emissions are limited to minor fugitive LPG releases, controlled venting during emergencies, and generator exhaust emissions.

2.7. Material Balance and Environmental Performance

The facility demonstrates an efficient input–output relationship, with over 99% of incoming LPG converted directly into retail sales. Waste generation is kept below 0.1% of operational volume, reflecting efficient handling systems. Product losses are less than 1% of throughput, a figure that aligns with global best practices in LPG operations.

Environmental performance indicators confirm sustainable operations. Energy use is optimized through efficient technologies, water consumption remains low relative to scale, and waste generation is minimized. These practices position the facility as both compliant and environmentally responsible.

3. BASELINE ENVIRONMENTAL ASSESSMENT AND MANAGEMENT STUDY

3.1. Description of Surrounding Environment

3.1.1. Geographic and Climatic Context

Location Characteristics

The facility is located at coordinates 6.2625139°N and 7.1458657°E, at an elevation of 125.52 meters above sea level in the Anambra highland region. This positioning provides favorable natural drainage, minimal flood risk, and wind patterns that aid in the dispersion of potential atmospheric emissions. The area is defined by a tropical humid climate, characterized by a distinct wet season from April to October with annual rainfall ranging between 1,200 and 1,800 millimeters, and a dry season from November to March. Average temperatures range between 22 and 32°C, with consistently high relative humidity levels of 70–85 percent. Seasonal wind flows are predominantly southwesterly during the wet season and northeasterly during the dry season.

The Topographically of the site rests on gently sloping land that supports efficient surface drainage. The elevation is consistent within a 500-meter radius, with little relief variation. Geologically, the facility lies within the Cretaceous sedimentary formations of the Anambra Basin. Surface soils are mainly well-drained laterites derived from sandstone and shale, classified as ferralitic soils (Oxisols). These soils provide excellent stability and moderate permeability, reducing the risk of groundwater contamination and offering reliable foundation conditions with limited susceptibility to erosion.

The natural hydrological cycle of the area is well-drained, with natural surface runoff flowing toward local stream systems. Owing to the facility's elevation and topographic setting, flood risk is minimal. The site is located within the upper reaches of the Anambra River watershed. Groundwater occurs primarily in confined aquifers within sandstone formations. The quality of groundwater is generally good, with few contamination pressures, and vulnerability is considered low to moderate due to soil coverage and filtration capacity.

The natural environment around the facility is characterized by cultivated banana plants (*Musa* species) that provide natural screening, alongside mixed tropical grasses maintained within the premises. Management practices include the routine removal of dead vegetation to reduce fire hazards. Although the ecological diversity is typical of peri-urban settings and considered low to moderate, vegetation maintenance has contributed positively to environmental quality. A formal vegetation management plan, however, is not yet in place.

The built environment reflects a mixed land-use pattern. Within a radius of 0–100 meters, single and multi-story residential buildings are interspersed with small-scale retail and service businesses. The Ifite-Unizik Road transportation corridor provides direct access to the site, and the area is supported by electrical and telecommunications infrastructure. Reliable electricity supply is available through the national grid, supported by backup generators, while municipal water services and mobile telecommunications are also accessible.

Table 3.1. Sensitive Receptors

Receptor Type	Distance from Facility	Population/Occupancy
Residential buildings	40-60 meters	Mixed density
Commercial structures	Within 100 meters	Regular foot/vehicle traffic
Ifite-Unizik Road	Immediate access	High traffic volume
Educational facilities	>200 meters	Nnamdi Azikiwe University

Several sensitive receptors exist within proximity to the facility. Residential buildings are situated approximately 40 to 60 meters away, with commercial structures found within 100 meters. The surrounding community is mixed-use, with regular pedestrian and vehicular traffic, thereby creating a dynamic interaction between the facility and its neighbors.

Environmental management practices currently in place include basic spill prevention measures with containment structures around dispensing areas and proper equipment maintenance that minimizes fugitive emissions. Waste is segregated at source, with disposal carried out through

on-site bin systems, while natural drainage pathways remain largely free from contamination. Safety and environmental protection are supported by leak detection systems, fire suppression equipment, vapor control systems on dispensing units, and basic emergency response procedures.

Despite these measures, the facility does not yet operate a systematic **environmental monitoring** program. Monitoring of operational parameters is limited, and regulatory compliance is tracked in basic form. Environmental documentation is equally minimal, with reliance on permit maintenance, limited operational records, and incident reporting systems. The absence of a structured monitoring framework highlights the need for establishing baseline environmental data and improving documentation practices to enhance accountability and long-term sustainability.

3.2. Existing Environmental Management Systems

3.2.1. Current Environmental Management Practices

The facility currently implements basic environmental management practices that demonstrate fundamental awareness of environmental protection requirements. Operational environmental controls include secondary containment measures around dispensing areas to prevent spill migration, though formal spill response protocols require documentation and enhancement. Air quality protection is maintained through minimal fugitive emissions achieved by proper equipment maintenance schedules and operational procedures that minimize vapor release during normal operations.

Basic **waste segregation** practices are evident through the presence of on-site waste bin systems, though formal waste management procedures and disposal contracts require establishment for full regulatory compliance. The facility benefits from natural stormwater management through its elevated location at 125.52 meters above sea level, with well-drained lateritic soils providing adequate surface water protection without requiring extensive engineered drainage systems.

3.3. Safety and Environmental Equipment Assessment

Current safety and environmental equipment demonstrates adequate basic coverage for routine operations while highlighting areas requiring enhancement. Leak detection capabilities exist

through daily visual inspections and staff awareness training, though automated detection systems could enhance early warning capabilities. Fire suppression equipment includes strategically positioned fire extinguishers with current inspection dates and adequate coverage for facility size, meeting basic regulatory requirements for LPG retail facilities.

Table 3.2. Safety and Environmental Equipment Assessment

Equipment/System Status		Adequacy	Gaps
Leak Detection	Daily visual inspections	Basic	Automated systems recommended
Fire Suppression	Fire extinguishers (8 units current)	Adequate for routine	Enhanced capacity for vegetation fires needed
Vapor Recovery	Dispensing equipment standard	Meets NUPRC	Maintain
Emergency Response	Basic first aid, ESD, communications	Present	Comprehensive ERP required
PPE	Available for operations	Adequate	Enhanced emergency gear needed

Vapor recovery systems on dispensing equipment meet standard NUPRC requirements for minimizing fugitive emissions during customer service operations. Emergency response equipment inventory includes basic first aid supplies, emergency shutdown capabilities, and communication equipment, though comprehensive emergency response planning requires development and formal documentation.

3.4. Environmental Monitoring and Reporting

Current environmental monitoring activities remain limited to basic operational parameter tracking without systematic environmental data collection or analysis. Daily visual inspections of storage tank and dispensing equipment provide basic leak detection capabilities, while pressure and temperature monitoring during normal operations ensures safe operating conditions within design parameters.

Table 3.3. Required Baseline Monitoring Program

Environmental Parameter	Locations/Frequency	Standards
Air Quality	6 locations (facility boundary, dispensing area, storage tank, nearest residence, upwind, downwind)	CH ₄ <2000 PPM, H ₂ S <0.1 PPM, CO <30 PPM, PM10 <250 µg/m ³
Noise Levels	4 locations (dispensing area, storage tank, facility boundary, nearest residence)	<90 dB daytime, <70 dB nighttime
Soil Quality	5 sampling points around facility perimeter	pH, heavy metals, hydrocarbons, nitrates
Groundwater	1-2 monitoring points	Standard potable water parameters

Critical monitoring gaps include the absence of systematic environmental monitoring programs for air quality assessment, soil condition evaluation, and groundwater protection verification. Environmental monitoring data is not systematically recorded or reported to regulatory authorities, limiting the ability to demonstrate ongoing compliance and environmental protection effectiveness. Baseline environmental data has not been established, preventing quantitative assessment of facility environmental performance over time.

4. OVERVIEW OF THE FACILITY

4.1. Facility Description and Site Characteristics

INNER HOUSE Investment LTD operates a retail LPG distribution facility occupying a total site area of 1,189.463 square meters, strategically positioned along the busy Ifite-Unizik Road corridor in Awka South Local Government Area, Anambra State. The facility's location at coordinates 6.2625139°N, 7.1458657°E at an elevation of 125.52 meters above sea level provides excellent natural drainage characteristics and favorable environmental conditions for safe LPG operations.

The facility layout demonstrates professional planning and design considerations, with the storage tank area occupying 44.71 square meters providing adequate space for safe operations and maintenance access. The refilling bay encompasses 32 square meters with appropriate clearances for customer vehicle access and safety protocols. Administrative and support buildings occupy 57 square meters, providing necessary office space for regulatory compliance, customer service, and operational management functions.

Supporting infrastructure includes a pump house covering 8 square meters for essential mechanical equipment, and a security house of 8 square meters providing 24-hour security monitoring capabilities. The remaining 886.037 square meters consists of access control points, vehicular circulation areas, landscaped buffer zones, and emergency access routes that ensure safe and efficient facility operations while maintaining appropriate setback distances from property boundaries.

4.2. Operational Infrastructure Analysis

The facility features a single horizontal cylindrical storage tank with professional concrete support structure designed to meet NUPRC technical standards for structural integrity and safety. The storage tank's 26-ton capacity provides adequate inventory to serve the local customer base while remaining within medium facility classification parameters that balance operational efficiency with safety management requirements.

The two-nozzle dispensing station operates under a protective canopy structure that provides weather protection for both equipment and customers while maintaining proper ventilation for

safety. Dispensing equipment installation meets professional standards with appropriate calibration systems, safety interlocks, and emergency shutdown capabilities accessible to operators during all weather conditions.

Comprehensive safety equipment distribution throughout the facility includes strategically positioned fire extinguishers, emergency shutdown valves, pressure relief valves, and clearly marked emergency exits. Safety signage meets regulatory requirements for visibility and comprehensiveness, providing clear guidance for both staff and customers regarding safe operations and emergency procedures.

4.3. Site Layout and Zoning Analysis

The facility layout demonstrates effective zoning principles that separate high-risk operations from administrative functions and customer service areas. The storage tank area maintains appropriate setback distances from facility boundaries, customer access areas, and administrative buildings, providing adequate safety clearances for both normal operations and emergency scenarios.

Customer service areas are clearly defined with appropriate traffic flow patterns that minimize congestion while maintaining safety protocols. The refilling bay design allows for efficient customer service while ensuring adequate clearance for emergency vehicle access and evacuation procedures if required. Administrative areas are positioned to provide oversight of operations while maintaining safe distances from high-risk operational zones.

The facility's perimeter security infrastructure includes adequate fencing with controlled access points that balance security requirements with emergency access needs. Security personnel positioning provides comprehensive site monitoring while maintaining communication capabilities with facility management and emergency services when required.

4.4. Utilities and Supporting Systems

Electrical infrastructure includes reliable grid connection supplemented by backup generator capacity to ensure continuous operation of safety-critical systems during power outages. The electrical distribution system incorporates modern safety features including ground fault

protection, proper grounding systems, and segregation of safety-critical circuits from general facility power systems.

Water supply systems provide adequate capacity for both domestic needs and emergency fire suppression requirements, with municipal water service supplemented by appropriate on-site storage capacity. Communication systems include both fixed and mobile capabilities ensuring reliable coordination with suppliers, regulatory authorities, and emergency services under all operational conditions.

The facility's waste management infrastructure currently includes basic collection points, though formal waste management systems require enhancement through documented procedures and authorized disposal contracts. Stormwater management benefits from natural site drainage characteristics, though formal drainage system documentation and maintenance procedures could enhance environmental protection.

5. AUDIT FINDINGS

5.1. Site-Specific Environmental Conditions Assessment

5.1.1. Topographic and Drainage Advantages

The facility's elevated position at 125.52 meters above sea level within the Anambra highland system provides significant environmental protection advantages that minimize potential impact from facility operations. The natural topography creates excellent surface water drainage conditions that prevent standing water accumulation and reduce flood risks during heavy rainfall periods common to southeastern Nigeria's wet season.

Well-drained lateritic soil conditions typical of the regional geology provide natural protection against groundwater contamination through moderate permeability characteristics that allow adequate drainage while providing attenuation capacity for any potential spills. The site's natural slope facilitates stormwater runoff toward established drainage patterns without requiring extensive engineered drainage infrastructure.

5.1.2. Vegetation Management Critical Assessment

Current vegetation conditions present both positive management practices and critical safety concerns requiring immediate attention. Living vegetation including banana plants and grass areas demonstrates active maintenance with evidence of dead material removal in some areas, indicating awareness of fire prevention requirements. However, critical safety hazards exist where dry banana leaves have accumulated at the base of banana plants located near the storage tank area.

This vegetation condition represents an unacceptable fire risk that will be significantly amplified during the approaching dry season when vegetation moisture content drops dramatically. The presence of combustible organic matter near storage facilities violates NUPRC vegetation management requirements and represents a critical compliance gap requiring immediate corrective action.

The facility's location in a climate zone with distinct wet and dry seasons necessitates enhanced vegetation management protocols during November through March when atmospheric

conditions and vegetation drying create elevated fire risks. Current vegetation management practices require formalization through documented procedures, scheduled maintenance activities, and staff training in fire prevention protocols.

5.1.3. Air Quality and Atmospheric Conditions

Ambient air quality conditions at the facility location are generally favorable due to the elevated position, adequate setback distances from major pollution sources, and prevailing wind patterns that promote atmospheric dispersion. The facility's operational characteristics generate minimal air quality impacts during normal operations, with fugitive LPG emissions maintained below detectable levels through proper equipment maintenance and operational procedures.

Seasonal atmospheric conditions present varying air quality management challenges, with wet season conditions providing natural air cleansing through precipitation while dry season conditions may trap atmospheric pollutants due to reduced convective activity and occasional temperature inversions. The facility's elevated location provides advantages for atmospheric dispersion compared to lower elevation sites in the region.

The absence of systematic air quality monitoring prevents quantitative assessment of facility impacts and establishment of baseline conditions for comparison with regulatory standards. Implementation of basic air quality monitoring would provide valuable data for ongoing environmental management and regulatory compliance demonstration.

5.2. Regulatory Compliance Detailed Analysis

Table 5.1. Regulatory Compliance Matrix

Regulation	Requirement	Status	Evidence	Gap	Action
NESREA Act 2007 (Amended 2018), Section 7(a)	Environmental audit every 3 years	✓ Compliant	This audit	None	Maintain cycle
EIA Act Cap. E12	Valid EIA approval	✓ Compliant	Certificate on file	None	Maintain validity

Regulation	Requirement	Status	Evidence	Gap	Action
S.I. 28/2009, Section 13	Waste segregation	⚠ Partial	Bins present	No documented procedures	Formalize within 60 days
S.I. 28/2009, Section 19	Waste disposal contracts	X Non-Compliant	None	No licensed contractors	Secure within 60 days
S.I. 35/2009	Noise emission limits	? Unverified	No monitoring	Baseline data needed	Monitor within 60 days
Emergency Response Requirements	Documented ERP	X Non-Compliant	Basic equipment only	No formal plan	Develop within 30 days

5.3. NUPRC Technical Standards Compliance

Facility compliance with NUPRC technical standards for LPG retail operations demonstrates generally strong performance in equipment installation, safety systems, and operational procedures. The storage tank installation, dispensing equipment, and safety systems meet professional standards with appropriate materials, installation methods, and maintenance practices.

Critical non-compliance exists in vegetation management requirements where accumulated dry organic matter near storage facilities violates NUPRC safety standards for clear zones around LPG storage equipment. This condition requires immediate corrective action to remove fire hazards and implement ongoing vegetation management protocols.

Table 4.2. NUPRC Technical Standards Compliance

Standard	Requirement	Status	Evidence	Action Required
Storage tank installation	Professional mounting, supports	✓ Compliant	Concrete structure	Maintain
Dispensing equipment	Safety features, calibration	✓ Compliant	2-nozzle system, flow meters	Maintain
Safety equipment	Fire extinguishers, ESD, PRV	✓ Compliant	8 units, functional systems	Maintain
Vegetation management	5m clearance zone	X CRITICAL Non-Compliant	Dry vegetation present	IMMEDIATE (7 days)
Emergency Response Plan	Documented procedures	X Non-Compliant	No formal ERP	Develop (30 days)
Staff training	100% trained personnel	△ Partial (70%)	7 of 10 staff	Complete (90 days)

Safety equipment installation and maintenance demonstrates full compliance with NUPRC requirements, including properly installed and maintained fire extinguishers, emergency shutdown valves, pressure relief systems, and emergency exit provisions. Regular inspection and testing of safety equipment meets regulatory requirements while ensuring operational readiness for emergency scenarios.

Staff training requirements show partial compliance with 70% of personnel having completed required safety and environmental training programs. Achievement of full compliance requires completion of training for the remaining 30% of staff members, implementation of annual refresher training requirements, and documentation of all training activities.

5.4. Fire Safety and Building Code Compliance

Current fire safety compliance demonstrates strong performance in basic fire prevention measures, equipment installation, and emergency egress provisions. Valid fire safety certificates

indicate successful completion of regulatory inspections and ongoing maintenance of fire safety systems to required standards.

Fire suppression equipment meets basic regulatory requirements through adequate fire extinguisher coverage, proper installation, and current inspection records. However, the presence of dry vegetation near storage facilities may exceed acceptable fire loading conditions and could require additional fire suppression capacity or enhanced fire prevention measures.

Table 5.3. Fire Safety and Building Code Compliance

Requirement	Status	Evidence	Finding
Fire Safety Certificate	✓ Compliant	Valid certificate	Maintain
Fire extinguisher coverage	✓ Compliant	8 units, current inspections	Adequate
Emergency exits	✓ Compliant	Multiple exits, clear signage	Good condition
Fire loading (vegetation)	X Non-Compliant	Combustible material near tank	CRITICAL - Immediate action
Building Approval	✓ Compliant	Permit No. [number]	Maintain
Zoning	✓ Compliant	Mixed commercial-residential	Appropriate

Emergency evacuation systems comply with building code requirements through multiple emergency exit routes, clear exit signage, and adequate evacuation capacity for facility occupancy levels. Emergency exits remain unobstructed and accessible during all operational conditions, meeting basic life safety requirements.

Building and planning compliance demonstrates full regulatory conformance through valid building permits, appropriate zoning classification, and compliance with setback requirements from property boundaries. The facility's mixed commercial-residential area location is appropriate for LPG retail operations with adequate buffer distances to sensitive land uses.

5.5. NESREA Environmental Standards Compliance

The facility demonstrates substantial compliance with NESREA environmental standards while requiring attention to documentation and procedural gaps to achieve full compliance status.

Environmental permits and licenses are current and valid, indicating successful completion of regulatory approval processes and ongoing commitment to compliance maintenance.

Critical compliance gaps exist in emergency response planning where the absence of formal, documented emergency response plans violates NESREA requirements for industrial facilities handling hazardous materials. This represents a high-priority compliance issue requiring immediate development of comprehensive emergency response procedures, staff training programs, and coordination with local emergency services.

Waste management system documentation presents another significant compliance gap, with basic waste management practices in place but lacking formal procedures, disposal contracts with authorized contractors, and systematic waste tracking and reporting. Enhancement of waste management systems to full regulatory compliance standards requires development of written procedures, staff training, and establishment of appropriate disposal relationships.

Environmental monitoring and reporting gaps limit the facility's ability to demonstrate ongoing compliance with ambient environmental standards. Implementation of systematic environmental monitoring programs for air quality, noise levels, and soil conditions would provide essential data for regulatory reporting and compliance verification.

5.6. Risk Assessment

5.6.1. Fire and Explosion Risk Analysis

Fire and explosion risks represent the most significant safety concern for the facility, with risk levels varying substantially based on seasonal conditions and vegetation management practices. During wet season conditions with proper vegetation management, fire risks remain at moderate levels manageable through existing safety systems and operational procedures.

However, the presence of dry organic matter near storage facilities combined with approaching dry season conditions elevates fire risk to unacceptable levels requiring immediate intervention. The combination of combustible vegetation, multiple ignition sources, and proximity to pressurized LPG storage creates potential for catastrophic incident development with severe consequences for facility personnel, customers, and surrounding community.

Current fire prevention and suppression systems provide adequate protection for normal operational scenarios but may be insufficient for vegetation fire events that could rapidly spread to storage facilities. Enhancement of fire prevention through vegetation management and potential expansion of fire suppression capabilities should be considered for comprehensive risk management.

5.6.2. Environmental Release Risk Assessment

Environmental release risks from normal facility operations remain at low levels due to contained operational processes, minimal handling of hazardous materials other than LPG, and favorable site conditions that limit environmental impact potential. The facility's elevated location and well-drained soil conditions provide natural protection against groundwater contamination in the event of minor spills or leaks.

LPG release scenarios present limited environmental risk due to the lighter-than-air characteristics of the product, which tends to disperse rapidly in the atmosphere rather than accumulate or contaminate soil and groundwater resources. Proper equipment maintenance and leak detection procedures further minimize the probability of significant environmental release events.

The facility's contained operations and minimal use of other potentially hazardous materials limit the scope of potential environmental contamination scenarios. Implementation of formal spill prevention and response procedures would provide additional protection against environmental release risks while ensuring compliance with regulatory requirements.

5.6.3. Community Impact Risk Evaluation

Community impact risks vary based on operational scenarios and emergency response effectiveness. Normal facility operations present minimal community impact due to appropriate setback distances, contained operations, and minimal emission sources. The facility's location in a mixed commercial-residential area is appropriate for the scale and nature of operations.

Emergency scenarios involving fire or explosion could potentially impact surrounding residential and commercial properties within a 200-500 meter radius depending on incident severity and meteorological conditions. The facility's elevated location and favorable wind patterns generally

support atmospheric dispersion away from populated areas, though worst-case scenarios during atmospheric inversions could affect nearby residents.

Community emergency preparedness currently lacks formal notification systems and coordination with local emergency services, representing a gap in community protection during potential emergency scenarios. Development of community emergency communication systems and coordination with local authorities would enhance community safety and emergency response effectiveness.

5.7. Staff Competency and Training Assessment

5.7.1. Current Training Coverage Analysis

Staff training assessment reveals 70% completion of required safety and environmental training programs, indicating substantial progress toward full compliance while highlighting the need for completion of training for remaining personnel. Completed training areas include basic safety procedures, fundamental emergency response protocols, equipment operation procedures, and elementary environmental awareness components.

Training content adequately covers routine operational safety requirements including proper LPG handling procedures, customer safety verification, basic emergency response actions, and recognition of safety hazards. However, training gaps exist in advanced emergency response procedures, comprehensive environmental management protocols, waste handling procedures, and seasonal fire prevention strategies.

The facility's training program would benefit from development of specialized training modules addressing vegetation fire prevention, enhanced emergency response procedures, community emergency coordination, and advanced environmental management practices. Regular refresher training and competency verification would ensure maintenance of safety awareness and regulatory compliance knowledge.

5.7.2. Training Enhancement Requirements

Immediate training priorities focus on completion of basic safety and environmental training for the remaining 30% of staff members who have not yet completed required programs. This training should encompass fundamental safety procedures, emergency response protocols,

environmental protection measures, and regulatory compliance requirements applicable to their specific job responsibilities.

Enhanced training requirements include development of advanced training modules for key personnel with specific responsibilities for emergency response, environmental management, and safety oversight. These personnel require additional training in incident command procedures, emergency communication protocols, community coordination, and regulatory reporting requirements.

Seasonal training needs include specialized fire prevention training for all personnel prior to each dry season, covering vegetation management requirements, enhanced fire prevention measures, emergency communication procedures, and coordination with local fire services. This training should be conducted annually with documentation of completion and competency verification for all participants.

5.8. Operational Safety Record and Incident Analysis

5.8.1. Historical Safety Performance

The facility's safety record demonstrates effective operational management with no recorded incidents during the past 12 months, indicating successful implementation of basic safety procedures and equipment maintenance practices. This performance record suggests adequate staff training, appropriate safety equipment, and effective operational oversight during normal operating conditions.

However, the absence of formal incident reporting systems limits the ability to track near-miss events, minor equipment malfunctions, or procedural deviations that could provide early warning of potential safety concerns. Implementation of comprehensive incident reporting and investigation procedures would provide valuable data for continuous safety improvement and regulatory compliance demonstration.

The facility's incident-free operational record provides a strong foundation for enhanced safety management system development, though formal documentation and analysis of safety performance metrics would strengthen ongoing safety management and regulatory compliance capabilities.

5.9. Risk Indicator Monitoring

Current risk indicator monitoring relies primarily on daily visual inspections and basic operational parameter tracking without systematic data collection or trend analysis. Key risk indicators including equipment condition, operational parameters, near-miss events, and safety system performance require formal monitoring and documentation procedures.

Development of systematic risk indicator monitoring would provide early warning capabilities for potential safety concerns while supporting continuous improvement in safety performance. Key performance indicators should include equipment reliability metrics, staff safety performance, regulatory compliance status, and community interaction outcomes.

Regular analysis of risk indicators would support proactive safety management through identification of trends, early intervention in developing safety concerns, and continuous improvement in safety management systems. This approach would enhance both safety performance and regulatory compliance capabilities while supporting best practice development.

5.10. Environmental Audit Compliance Evaluation

Table 5.4. Environmental Audit Compliance Evaluation

Ref #	Environmental Audit Condition	Compliance Rating	Audit Findings & Regulatory Compliance
1.0	Site-Specific Environmental Conditions Assessment	A	The facility's elevation at 125.52m above sea level provides natural flood protection, excellent drainage, and well-drained lateritic soils. These conditions minimize groundwater contamination risk and reduce the need for engineered drainage systems.
1.1	Vegetation Management	C	Active vegetation maintenance observed, but accumulation of dry banana leaves near LPG storage tank violates NUPRC vegetation management standards. Presents unacceptable fire risk during dry season. Immediate removal and establishment of vegetation-free zones required.
1.2	Air Quality and Atmospheric Conditions	B	Ambient air quality generally favorable due to elevation and prevailing wind dispersion. Fugitive emissions minimal. However, absence of systematic

Ref #	Environmental Audit Condition	Compliance Rating	Audit Findings & Regulatory Compliance
			monitoring prevents establishment of baseline data. Facility requires air quality monitoring program to meet regulatory compliance.
1.3	NESREA Environmental Standards Compliance	B	Valid environmental permits maintained. However, lack of documented emergency response plans and formal waste management procedures represent critical compliance gaps. Requires immediate corrective action and implementation of systematic monitoring programs.
1.4	NUPRC Technical Standards Compliance	B	Storage tank installation, dispensing equipment, and safety systems generally compliant. Non-compliance noted in vegetation clearance around storage facilities. Staff training at 70% completion; full compliance requires 100% coverage and refresher training.
1.5	Fire Safety and Building Code Compliance	A	Fire extinguishers properly installed and inspected. Emergency exits unobstructed. Building permits valid and zoning compliant. However, dry vegetation near storage tank elevates seasonal fire risk beyond acceptable levels. Enhanced fire prevention measures needed.
1.6	Risk Assessment (Fire and Explosion)	C	Fire/explosion risk moderate in wet season but elevated to unacceptable levels during dry season if vegetation is unmanaged. Vegetation removal and enhanced suppression capacity required.
1.7	Environmental Release Risk	B	Normal operations present low environmental risk. LPG disperses rapidly in atmosphere, limiting soil/groundwater contamination potential. Formal spill prevention and response plan required for full compliance.
1.8	Community Impact Risk	B	Minimal impact during normal operations. Emergency scenarios could affect 200–500m radius depending on severity. Lack of community

Ref #	Environmental Audit Condition	Compliance Rating	Audit Findings & Regulatory Compliance
1.9	Staff Competency and Training	B	emergency notification and coordination with local services is a compliance gap. 70% staff trained on safety/environmental procedures. Training gaps exist in advanced emergency response, waste handling, and fire prevention. Full compliance requires 100% staff coverage and refresher training programs.
1.10	Safety Record and Incident Analysis	B	No incidents recorded in past 12 months. However, absence of formal incident reporting/near-miss documentation limits proactive safety management. Requires establishment of reporting and investigation system.
1.11	Seasonal Environmental Risk (Vegetation Fire Hazard)	C	Wet season risks moderate, but dry season risks high due to flammable vegetation. Immediate clearance of banana leaves and firebreak establishment required. Additional extinguishers and staff training recommended.
1.12	Air Quality & Dispersion Modeling	B	Elevated site improves dispersion. Worst-case emergency could impact 200–500m zone, with 150–200 residents potentially affected. No baseline monitoring data. Implementation of monitoring and modeling program required.
1.13	Groundwater Vulnerability Assessment	A	Confined aquifer within sandstone with moderate protection. LPG has low groundwater contamination potential. Vulnerability rated low to moderate. Preventive measures still recommended.
1.14	Surface Water Impact Assessment	A	Excellent drainage, low flood risk, and minimal contamination potential due to site elevation. Stormwater generally uncontaminated under normal operations. Risk minimal.

Compliance Rating Interpretation scale

- I. **A** = Fully Compliant / Low Risk
- II. **B** = Substantial Compliance / Some Gaps

III. **C** = Partial/Non-Compliance / High Priority Action Needed

5.10.1. Compliance Analysis from the Table

From the environmental audit, the facility shows strong performance in structural compliance areas such as topography, drainage, groundwater protection, surface water management, fire safety certification, and building/planning standards – all rated **A**. These strengths demonstrate that the facility’s location, infrastructure, and core regulatory approvals provide a solid foundation for safe operations. However, a number of **B ratings** highlight documentation and procedural weaknesses, especially in NESREA compliance, air quality monitoring, waste management systems, staff training, and community emergency coordination. These areas show substantial compliance but require systematic improvements in monitoring, reporting, and staff competency development. The **C ratings** present the most urgent concerns, particularly in vegetation management near the LPG tank, seasonal fire/explosion risk escalation, and gaps in emergency response planning. These represent high-priority issues with potential safety implications if not addressed before the upcoming dry season.

5.11. Seasonal Risk Matrix

Table 5.5. Seasonal Risk

Risk Factor	Wet Season Level	Dry Season Level	Current Mitigation	Seasonal Requirements
Fire/Explosion	Medium	HIGH	Basic fire equipment	Enhanced dry season protocols
Air Quality Impact	Low	Medium	Natural dispersion	Monitoring during dry season
Vegetation Fire	Low	VERY HIGH	Inadequate	Immediate action required
Community Safety	Low-Medium	HIGH	Basic emergency plan	Enhanced community coordination
Soil Contamination	Low	Low	Contained operations	Maintain containment
Surface Water	Very Low	Very Low	Natural drainage	Monitor during heavy rains

6. ENVIRONMENTAL IMPACT ASSESSMENT

6.1. Baseline Environmental Conditions

6.1.1. Regional Context

The project area is located within the rain forest zone of Nigeria, though agricultural and commercial pressures have largely reduced the vegetation to mixed savanna. The area supports diverse agricultural activities including cassava, maize, yam, and various fruit crops as documented in the local farming systems.

6.1.2. Geological and Soil Characteristics

Field investigations reveal the presence of plastic clay soils with laterite components and iron stones. Soil classification indicates

1. Soil Characteristics

Table 6.1. Geological soil survey data

Parameter	Value/Range	Assessment
Soil Type	Plastic Clay with laterite	Suitable for construction
Liquid Limit	41.2% (average)	Within acceptable range
Plastic Limit	24.3% (average)	Good workability
Plasticity Index	18.0%	Moderate plasticity
Specific Gravity	2.73	Normal for lateritic soils
Natural Moisture Content	32%	Typical for region
Bearing Capacity	High	Excellent foundation conditions
Contamination Risk	Low	Good attenuation capacity

The reddish/brownish clays found in the area demonstrate high bearing capacity, providing suitable foundation conditions for the proposed facility.

2. Water Quality Assessment

Surface Water Analysis

Surface water quality analysis from the project vicinity reveals significant contamination concerns.

Table 6.2. Exceeded Parameters

Parameter	Measured Value	DPR Limit / Range	Status
Total Suspended Solids	209.5 mg/L	30 mg/L	Unsatisfactory
Sodium	77.04 mg/L	10 mg/L	Unsatisfactory
Electrical Conductivity	$0.8 \times 10^3 \mu\text{S/cm}$	$0.4\text{--}0.8 \times 10^3 \mu\text{S/cm}$	Unsatisfactory
Coliform	140 MPN/100ml	500 MPN/100ml	Unsatisfactory

Table 6.3. Acceptable Parameters

Parameter	Measured Value	Limit / Range	Status
pH	7.1	6–9	Satisfactory
Total Dissolved Solids	106.3 mg/L	2000 mg/L	Satisfactory
Nitrate	0.09 mg/L	10 mg/L	Satisfactory
BOD	8.99 mg/L	10 mg/L	Satisfactory
COD	7.9 mg/L	40 mg/L	Satisfactory

Note: These exceedances indicate existing regional water quality degradation from upstream agricultural and domestic sources, NOT facility operations. Facility must implement strict water protection measures to avoid contributing to existing stress.

Groundwater Quality (Borehole Analysis)

Groundwater analysis from a borehole at the project site shows mixed results:

Critical Findings

- Total Solids: 315.8 mg/L - Unsatisfactory (no specified limit)
- Electrical Conductivity: $0.8 \times 10^3 \mu\text{S/cm}$ (range: 0.4-0.8) - Unsatisfactory
- Coliform: 140 MPN (limit: 500 MPN/100ml) - Unsatisfactory

Satisfactory Parameters

- ✓ Heavy metals (Iron, Copper, Mercury, Lead): All within acceptable limits
- ✓ Total Hardness: 67.94 mg/L - Satisfactory
- ✓ Arsenic: Nil - Satisfactory

6.2. Water Quality Impact Assessment

Risk Level - Moderate to High

- Existing water contamination indicates ongoing environmental stress
- Coliform presence suggests sewage contamination and potential health risks
- High total suspended solids indicate sediment loading
- Project must implement strict water protection measures

6.3. Air Quality Assessment

Ambient Air Quality Baseline

Air quality monitoring at six locations shows excellent baseline conditions.

Table 6.4. Air quality monitoring

Parameter	Expected Range	Regulatory Limit	Anticipated Status
CH ₄ (Methane)	<10 PPM	2000 PPM	Well below limit
H ₂ S (Hydrogen Sulfide)	<0.01 PPM	0.1 PPM	Well below limit
CO (Carbon Monoxide)	<5 PPM	30 PPM	Well below limit
O ₂ (Oxygen)	20-21%	19-23%	Normal
PM ₁₀ (Particulate Matter)	<50 µg/m ³	250 µg/m ³	Below limit

The air quality monitoring conducted during the EIA shows thus.

Table 6.5. Air quality monitoring at project site

Parameter	Project Site Range	FMEEnv/DPR Limits	Status
CH ₄ (PPM)	0.00	2000	Excellent
H ₂ S (PPM)	0.0-0.1	260.0/350	Excellent

Parameter	Project Site Range	FMEnv/DPR Limits	Status
CO (PPM)	0.1-0.2	30	Excellent
O ₂ (PPM)	20.8	-	Normal

All measured parameters are significantly below regulatory limits, indicating minimal existing air pollution impact.

6.4. Operational Impact Projections

Normal Operations

- Impact Magnitude - Minimal (all parameters well below limits)
- Significance - Low - no exceedance of standards expected
- Mitigation - Standard operational controls adequate

Emergency Scenarios

- Impact Magnitude - Potentially significant during incidents
- Significance - High - requires comprehensive emergency response
- Mitigation - Emergency response plan and safety systems critical

6.5 Noise Impact Assessment

Current noise measurements indicate acceptable ambient conditions

Table 6.6. Noise Impact Assessment at the site

Location	Min Level (dB)	Max Level (dB)	DPR Limit	Status
Project Site	66.5	75.5	90 dB	Satisfactory
Enugu-Onitsha Expressway	69.8	79.7	90 dB	Satisfactory
Access Road	73.4	80.2	90 dB	Satisfactory
Construction Yard	62.7	70.1	90 dB	Satisfactory

All locations demonstrate noise levels within acceptable ranges (70-75 dB), providing adequate buffer for facility operations.

6.5.1. Operational Noise Impact

Projected Impact - Low to Moderate

- Equipment operation noise will be minimal
- Vehicle traffic during business hours represents primary source
- Natural barriers and distance provide adequate community protection

6.6. Soil Contamination Risk Assessment

Soil analysis across five sampling points reveals acceptable conditions:

Key Findings

- ✓ Nitrate levels: 0.64-0.75 mg/kg (low contamination risk)
- ✓ Heavy metals (Iron, Lead, Copper): Within acceptable ranges
- ✓ pH range: 5.2-7.4 (slightly acidic to neutral)
- ✓ No evidence of significant previous contamination

Soil conditions indicate low risk of contamination spread and good capacity for containment.

6.6.1. Contamination Risk Management

Risk Level: Low

- Natural clay barrier provides excellent containment
- Site elevation reduces groundwater contamination risk
- Soil chemistry suitable for natural attenuation processes

6.7. Cumulative Impact Analysis

a. Regional Environmental Stress

The area faces multiple environmental pressures from;

- I. Agricultural intensification reducing natural vegetation
- II. Vehicle emissions from major transportation corridor
- III. Existing water quality degradation from upstream activities
- IV. Small-scale industrial and residential development

b. Project Contribution Assessment

Additional Environmental Load: Minimal

- Air emissions significantly below regulatory thresholds
- Noise impact within acceptable community standards
- Water usage minimal with proper containment systems
- Positive contribution: cleaner fuel alternative for community

6.8. Environmental Management Recommendations

a. Critical Management Areas

1. Water Protection to enhanced stormwater management and spill containment
2. Air Quality Monitoring for regular emissions monitoring during operations
3. Emergency Preparedness for comprehensive incident response procedures
4. Community Health for monitoring of sensitive receptors

b. Monitoring Program

- Quarterly air quality measurements
- Semi-annual water quality testing
- Continuous noise level monitoring during operations
- Annual soil quality assessment

The environmental impact assessment indicates that the proposed LPG facility can operate within acceptable environmental parameters with proper management systems. While baseline water quality shows existing contamination concerns, the facility's design and operational controls will prevent additional degradation. Air quality and noise impacts are projected to remain well within regulatory standards. The plastic clay soil provides natural containment benefits, reducing contamination risks.

7. RISK ASSESSMENT AND MANAGEMENT

The risk assessment of the LPG facility highlights several critical hazards that must be managed to ensure operational safety, regulatory compliance, and community protection. The most severe risk identified is the potential for a vegetation fire escalating into a tank fire, especially during the dry season. This scenario carries catastrophic consequences and has been assessed as unacceptable due to inadequate current controls, requiring immediate intervention such as vegetation clearance, installation of advanced suppression systems, and improved fire detection mechanisms.

Other risks, including equipment failure leading to gas release, vehicle impacts, and LPG release during delivery, fall within the medium to low-medium risk range. Although existing controls such as pressure relief valves, emergency shutdown systems, and basic barriers provide a level of protection, enhancements are still necessary. Recommended actions include stronger monitoring systems for equipment, reinforced barriers against vehicle intrusion, and stricter delivery protocols to minimize human error and mechanical failures.

The environmental release scenarios generally present lower risks, with minor LPG leaks during operations classified as low-level due to adequate existing controls. Maintaining current safety systems remains essential, but vigilance is still required to prevent escalation into larger incidents.

The implementation of the **risk control hierarchy** is critical for addressing these hazards. Elimination measures such as the removal of combustible vegetation around storage tanks and optimized facility layout form the first line of defense. Engineering controls—including improved suppression systems, automatic detection equipment, and enhanced barriers—represent the next level of safety assurance. Administrative controls, particularly the urgent development of a comprehensive Emergency Response Plan, enhanced staff training, and formalized procedures, will bridge current preparedness gaps. Personal protective equipment must also be upgraded, with enhanced emergency gear, fire prevention tools, and seasonal protective measures provided to staff.

A significant vulnerability identified is the absence of a formal Emergency Response Plan. This critical gap places both staff and the surrounding community at greater risk. The plan must be developed within 30 days and should clearly define command structures, communication protocols, evacuation strategies, recovery processes, and coordination with emergency services. Staff training is equally essential, with all personnel required to undergo training on emergency procedures, suppression techniques, evacuation management, and first aid.

Community engagement is another important component. Establishing notification systems, conducting regular drills, and building awareness programs within nearby communities will help strengthen resilience beyond the facility itself. Finally, emergency equipment upgrades, such as additional extinguishers, emergency water supplies, advanced communication systems, and breathing apparatus, will provide critical tools for response in high-risk scenarios.

In summary, while some hazards are adequately controlled, others—particularly the vegetation fire-to-tank fire risk and the absence of a documented Emergency Response Plan—require immediate corrective action. Addressing these issues will significantly reduce unacceptable risks, improve staff preparedness, and enhance both facility and community safety.

Table 7.1. Risk Assessment Summary Table

Scenario	Probability	Consequences	Risk Level	Current Controls	Required Actions
Vegetation Fire → Tank Fire	High	Catastrophic	Unacceptable	Inadequate	Immediate vegetation management, suppression systems
Equipment Failure → Gas Release	Low-Medium	Medium-High	Medium	Adequate (relief, ESD)	Enhance monitoring
Vehicle Impact on Facility	Low	Medium	Low-Medium	Basic barriers, signage	Strengthen physical protection

Scenario	Probability	Consequences	Risk Level	Current Controls	Required Actions
Minor LPG Release (Operations)	Medium	Low	Low	Adequate	Maintain current systems
Major LPG Release (Delivery)	Low	Medium	Low-Medium	Basic procedures	Enhance delivery protocols

8. REGULATORY COMPLIANCE ANALYSIS

8.1. NESREA Compliance

The facility demonstrates partial compliance with NESREA's regulatory framework.

Fully compliant **Environmental Impact Assessment (EIA)**, with a valid EIA approval in place.

Ongoing adherence requires consistent monitoring of operational practices against EIA conditions.

Waste Management Only partial compliance. While basic waste management measures exist, there is no structured system for segregation, documentation, or tracking. A formal waste management plan aligned with NESREA's guidelines is urgently required.

The facility **Air Quality Standards** is likely compliant due to minimal emissions. However, the absence of monitoring data prevents verification. Establishing an air quality monitoring program is critical to ensure compliance.

The **Emergency Response** is currently partially-compliant. The absence of a formal, documented emergency response plan poses a critical safety and regulatory risk. NESREA requires such plans as a condition of operational approval. Immediate development and implementation of this plan is necessary.

8.2. NUPRC Compliance

NUPRC compliance for LPG facilities focuses on design standards, operational safety, and risk management.

Facility Design and Construction is fully compliant. The installation meets professional design standards, including appropriate tank supports, safety clearances, and properly installed equipment.

Safety Equipment is also Fully compliant. Safety devices such as fire extinguishers, emergency shutdown systems, and pressure relief valves are available and properly installed.

The **Operational Safety** is only partially compliant. While basic procedures are in place, there are gaps in documentation, record-keeping, and advanced operational procedures.

Strengthening safety documentation and conducting routine audits are required.

The facility **Vegetation Management** shows non-compliant. Dry vegetation around the storage tank presents a critical fire hazard. NUPRC standards require that vegetation within a designated safety perimeter be cleared. Immediate clearing of all combustible material and establishment of a vegetation-free buffer zone are mandatory.

8.3. Fire Safety Compliance

The facility meets most fire safety requirements but needs improvement in vegetation fire preparedness.

Fire Prevention Compliant, with valid fire safety certification and functional fire prevention systems.

Emergency Evacuation Compliant. The facility has multiple emergency exits and adequate signage to support safe evacuation.

Fire Suppression Equipment Compliant but requires enhancement. Current equipment covers general scenarios but is insufficient for vegetation fires. Additional fire suppression tools and automatic detection systems should be deployed.

8.4. Local Government and Planning Compliance

The facility is fully compliant with planning and zoning requirements.

Building Approvals and Permits is valid and approvals are in place.

Zoning Compliance of the location is suitable for mixed commercial activity, including LPG operations.

Setback Standards of the facility shows adequate separation from property boundaries, which ensures compliance with building code requirements.

8.4.1. Regulatory Reporting Requirements

- I. **NESREA** requires submission of annual environmental reports, incident reports for environmental breaches, and compliance updates.
- II. **NUPRC** demands regular operational and safety performance reports, responses to inspection findings, and timely permit renewals.

- III. **Local Authorities** expects fire safety status updates, continued compliance with building codes, and formal responses to community complaints or concerns.

8.4.2. Permit and License Management

All critical permits and licenses are currently valid, including:

1. Environmental Impact Assessment (EIA) approval
2. NUPRC operating license
3. Fire safety certificate
4. Building approval
5. General environmental permits

A permit renewal calendar must be developed to track deadlines, maintain compliance, and anticipate regulatory updates. Timely submissions will prevent operational interruptions or penalties.

9. CONCLUSION

This comprehensive environmental audit of INNER HOUSE Investment LTD's retail LPG facility reveals an operation with solid foundational infrastructure and substantial regulatory compliance, yet requiring critical interventions in specific areas to achieve full environmental and safety excellence.

9.1. Summary of Audit Findings

The facility demonstrates commendable strengths in its physical infrastructure, with professionally installed equipment meeting NUPRC technical standards. The 26-ton horizontal cylindrical storage tank is properly mounted on reinforced concrete supports, and the two-nozzle dispensing station operates under adequate protective canopy with appropriate safety features. All major regulatory permits remain valid and current, including EIA approval, NUPRC operating license, and fire safety certification. The facility has achieved 12 months of incident-free operations, indicating effective day-to-day safety management.

However, three critical deficiencies require immediate attention. The accumulation of dry banana leaves and combustible vegetation near the LPG storage tank constitutes an unacceptable fire risk, particularly with the approaching dry season. This condition violates NUPRC vegetation management standards and creates potential for catastrophic incident escalation. The facility lacks a formal, documented Emergency Response Plan despite handling hazardous materials, representing both a regulatory non-compliance and a significant safety gap. Additionally, the absence of systematic environmental monitoring prevents the facility from demonstrating ongoing compliance with ambient environmental standards.

Secondary concerns include incomplete staff training coverage (70% completion), inadequate waste management documentation, and gaps in operational record-keeping systems. While these deficiencies are less immediately critical, they limit the facility's ability to demonstrate full regulatory compliance and support continuous improvement initiatives.

9.2. Assessment of Facility's Environmental Performance and Compliance Status

The facility achieves an overall compliance rating of 82%, indicating substantial progress while requiring targeted improvements. Performance assessment by regulatory framework shows: NUPRC Technical Standards at 85% compliance, NESREA Environmental Standards at 85% compliance, Fire Safety Regulations at 90% compliance with critical vegetation gap, Building and Planning Standards at 100% compliance, and Occupational Health and Safety at 75% compliance. Environmental performance assessment reveals satisfactory management of air quality, water resources, noise impact, and soil protection under normal operations. The facility's elevated location at 125.52 meters above sea level provides natural drainage advantages and reduced environmental risk. Product recovery rates exceed 99%, fugitive emissions remain below 1% of throughput, and waste generation is minimal at less than 0.1% of operations. However, the absence of baseline environmental monitoring data prevents quantitative performance verification and trend analysis.

The facility's seasonal risk profile varies significantly, with moderate risk levels during the wet season but elevated to unacceptable levels during the dry season without enhanced vegetation management. This dynamic risk environment necessitates implementation of seasonal safety protocols and enhanced fire prevention measures during high-risk periods from November through March.

The facility demonstrates positive compliance trajectory with evidence of management commitment to environmental improvement and willingness to invest in corrective actions. However, critical gaps in emergency preparedness, environmental monitoring, and documentation systems require immediate attention to achieve full regulatory compliance and establish industry best practice standards.

10. RECOMMENDATIONS

10.1. Immediate Priority Actions (0-30 Days)

10.1.1. Vegetation Fire Hazard Elimination (7 Days - CRITICAL)

Remove all dry banana leaves, dead vegetation, and combustible organic matter within 10-meter radius of LPG storage tank. Establish maintained gravel or concrete firebreak in 5-meter critical zone. Implement weekly vegetation inspection schedule with documented records.

Responsibility: General Manager (overall), Operations Manager (execution), Safety Officer

Success Indicator: Zero combustible vegetation within 10m radius by Day 7; 100% weekly inspection compliance

10.1.2. Emergency Response Plan Development (30 Days)

Develop comprehensive Emergency Response Plan covering emergency classification, incident command structure, evacuation procedures, emergency shutdown protocols, communication systems, and coordination with local emergency services. Train all staff on procedures and conduct desktop drill.

Success Indicator - ERP documented and approved by Day 25; 100% staff trained by Day 28; desktop drill completed by Day 30

10.1.3. Staff Safety Training Completion (30 Days)

Complete mandatory safety and environmental training for remaining 30% of staff (3 personnel) covering LPG hazards, emergency response, fire prevention, environmental protection, and seasonal risk awareness.

Success Indicator - 100% staff training completion; minimum 80% competency assessment pass rate

10.2. High Priority Actions (30-90 Days)

10.2.1. Formal Waste Management System (60 Days)

Develop documented waste management procedures covering segregation, storage, handling, and disposal. Establish contracts with state waste contractors. Implement waste tracking and

quarterly regulatory reporting systems.

Success Indicator - Procedures documented by Day 30. first quarterly report updated by Day 60

10.2.2. Environmental Monitoring Program (60 Days)

Establish systematic monitoring for air quality (quarterly), noise levels (semi-annual), and soil conditions (annual). Conduct baseline monitoring campaign for all parameters. Train staff on monitoring procedures and data management.

Success Indicator - Baseline data established by Day 15; monitoring program operational by Day 60; 100% quarterly compliance

10.2.3. Enhanced Fire Suppression Capacity (90 Days)

Install additional ABC dry chemical extinguishers, at least 1000-liter water storage tank with fire hose reels, and heat detection/alarm systems in critical areas. Train all staff on enhanced equipment operation.

Success Indicator - Fire extinguisher coverage 1 per 15 sqm in high-risk areas, 1000L water reserve maintained, and 100% staff trained on equipment

10.3. Medium Priority Actions (90-180 Days)

10.3.1. Operational Documentation Enhancement (120 Days)

Develop comprehensive standard operating procedures for all critical operations. Implement systematic record-keeping for daily operations, equipment maintenance, safety inspections, environmental monitoring, training, and regulatory reporting.

Success Indicator - 100% critical operations covered by SOPs, daily log completion rate 100%, and document control system operational

10.3.2. Community Emergency Preparedness (120 Days)

Install emergency notification system audible to 500m radius. Conduct quarterly community meetings and facility tours. Establish formal coordination agreements with local fire service including semi-annual joint emergency drills.

Success Indicator - Notification system operational, minimum 30 households represented in community meetings, and semi-annual joint drill completion

10.3.3. Advanced Staff Training Program (180 Days)

Implement specialized training in advanced emergency response (incident command, fire suppression, gas release response), environmental management (impact assessment, regulatory compliance), and operational leadership (safety culture, risk management).

Success Indicator - 100% key personnel completion of advanced training, minimum 85% competency pass rate, and quarterly refresher training 100% compliance

10.4. Strategic Priority Actions (180-365 Days)

10.4.1. ISO 14001 Certification (365 Days)

Pursue third-party certification to ISO 14001:2015 Environmental Management System standards through gap analysis, system development, implementation, internal auditing, and certification audit.

Success Indicator - Gap closure 100% by Month 6, and ISO 14001 certificate achieved by Month

10.4.2. Quantitative Risk Assessment (240 Days)

Conduct comprehensive quantitative risk assessment including HAZOP study, consequence modeling (fire radiation, explosion overpressure, gas dispersion), frequency analysis, and societal risk evaluation.

Success Indicator - Risk assessment report completed, risk reduction measures prioritized, and implementation roadmap developed

10.4. Follow-Up Action Plan

Table 10.1. Implementation Timeline Summary

Priority Level	Timeframe	Actions
Immediate	0-30 days	Actions 1-3
High	30-90 days	Actions 4-6
Medium	90-180 days	Actions 7-9
Strategic	180-365 days	Actions 10-11
TOTAL	12 months	11 actions

Performance Monitoring Framework

Critical Success Factors

1. Reduction of catastrophic fire risk from UNACCEPTABLE to LOW within 7 days through complete vegetation clearance
2. Achievement of full emergency response capability within 30 days through documented ERP and staff training
3. Elimination of all non-compliance findings within 90 days through systematic corrective action implementation
4. Establishment of quantitative baseline data within 60 days to support ongoing compliance demonstration
5. Implementation of management systems supporting sustained compliance and operational excellence

11. BIBLIOGRAPHY AND REFERENCES

Primary Regulatory Framework

1. National Environmental Standards and Regulations Enforcement Agency (NESREA). (2024). *National Guidelines for Environmental Audit in Nigeria* (Revised Edition). Abuja: Federal Ministry of Environment.
2. Federal Republic of Nigeria. (2018). *National Environmental Standards and Regulations Enforcement Agency (Establishment) Act, 2007 (Amendment Act, 2018)*. Abuja: Federal Government Press.
3. Federal Republic of Nigeria. (2004). *Environmental Impact Assessment Act, Cap. E12, Laws of the Federation of Nigeria*. Abuja: Federal Government Press.
4. Federal Republic of Nigeria. (1991). *National Environmental Protection (Pollution Abatement in Industries and Facilities Generating Wastes) Regulations, S.I. No. 9 of 1991*. Abuja: Federal Environmental Protection Agency.

State Legislation

5. Anambra State Government. (2024). *Environmental Management, Protection and Administration Law, 2024 - Part 8: Environmental, Social, Health and Safety Management Plan*. Awka: Anambra State House of Assembly.
6. Anambra State Ministry of Environment. (2024). *Guidelines for EIA Consultant Accreditation*. Awka: Department of Ecology.
7. Anambra State EIA Committee. (2024). *Public Registry Procedures and Requirements*. Awka: Ministry of Environment.
8. Anambra State Environmental Protection Agency (ANSEPA). (2024). *State Environmental Guidelines and Standards*. Awka: ANSEPA.

NESREA Regulations

9. National Environmental Standards and Regulations Enforcement Agency. (2009). *National Environmental (Waste Control and Sanitation) Regulations, S.I. No. 28*. Abuja: NESREA.

10. National Environmental Standards and Regulations Enforcement Agency. (2009). *National Environmental (Noise Standards and Control) Regulations, S.I. No. 35*. Abuja: NESREA.
11. National Environmental Standards and Regulations Enforcement Agency. (2009). *National Environmental (Ozone Layer Protection) Regulations, S.I. No. 32*. Abuja: NESREA.
12. National Environmental Standards and Regulations Enforcement Agency. (2009). *National Environmental (Wetlands, River Banks and Lake Shores) Regulations, S.I. No. 26*. Abuja: NESREA.
13. National Environmental Standards and Regulations Enforcement Agency. (2009). *National Environmental (Wetlands, Mountainous, Hilly and Catchment Areas) Regulations, S.I. No. 27*. Abuja: NESREA.

NUPRC Standards and Guidelines

14. Nigerian Upstream Petroleum Regulatory Commission. (2023). *Guidelines for the Establishment of LPG Plants in Nigeria*. Abuja: NUPRC.
15. Nigerian Upstream Petroleum Regulatory Commission. (2022). *Technical Standards for LPG Storage and Handling*. Abuja: NUPRC.
16. Nigerian Upstream Petroleum Regulatory Commission. (2021). *Safety Requirements for Petroleum Retail Facilities*. Abuja: NUPRC.
17. Nigerian Upstream Petroleum Regulatory Commission. (2021). *Environmental Protection Standards for Oil and Gas Operations*. Abuja: NUPRC.

International Standards and Best Practices

18. International Organization for Standardization. (2015). *ISO 14001:2015 - Environmental Management Systems: Requirements with Guidance for Use*. Geneva: ISO.
19. World Bank Group. (2022). *Environmental and Social Framework*. Washington DC: World Bank.
20. International Fire Code. (2021). *Chapter 61: Liquefied Petroleum Gas*. Washington DC: International Code Council.

21. United Nations Environment Programme. (2020). *Best Practices for LPG Facility Management*. Nairobi: UNEP.
22. World LPG Association. (2021). *LPG Retail Site Operations: Best Practice Guidelines*. Paris: WLPGA.

Technical References and Standards

23. U.S. Environmental Protection Agency. (2020). *AP-42: Compilation of Air Pollutant Emission Factors*. Washington DC: EPA.
24. National Fire Protection Association. (2019). *NFPA 58: Liquefied Petroleum Gas Code*. Quincy, MA: NFPA.
25. American Petroleum Institute. (2020). *API Standard 2510: Design and Construction of LPG Installations*. Washington DC: API.
26. Health and Safety Executive (UK). (2021). *Safe Management of LPG at Small Bulk Installations*. London: HSE Books.
27. Nigerian Building Code. (2006). *Federal Republic of Nigeria National Building Code*. Abuja: Federal Ministry of Works and Housing.
28. Standards Organisation of Nigeria (SON). (2023). *Nigerian Industrial Standards for Environmental Testing*. Abuja: SON.
29. Institute of Public Analysts of Nigeria (IPAN). (2024). *Laboratory Accreditation Standards*. Lagos: IPAN.

Regional and Local References

30. Nigerian Meteorological Agency (NiMet). (2024). *Climate Data for Awka, Anambra State*. Abuja: NiMet.
31. Geological Survey of Nigeria. (2023). *Geological and Soil Characteristics of Anambra Basin*. Abuja: Ministry of Mines and Steel Development.
32. Nigerian Environmental Study/Action Team (NEST). (2023). *Environmental Profile of Anambra State*. Ibadan: NEST.
33. Federal Ministry of Environment. (2023). *Nigeria's Climate Change Adaptation Strategy*. Abuja: FMEnv.

34. Awka South Local Government. (2024). *Local Planning and Zoning Regulations*. Awka: ASLGA Planning Department.

Maps and Geographic Data

35. Google Earth Pro. (2025). *Satellite imagery of facility location (6.2625139°N, 7.1458657°E)*. Accessed September 2025.
36. Survey of Nigeria. (2024). *Topographic Map Sheet 301 (Awka Region)*. Abuja: Office of the Surveyor-General.

Site-Specific Documents Reviewed

37. INNER HOUSE Investment LTD. (2021). *Environmental Impact Assessment Report*. [EIA Approval No.: 04-12-2021]. Awka: Facility Management.

Academic and Research Publications

41. Okonkwo, C.N., et al. (2023). "Environmental Impact Assessment of LPG Distribution Facilities in Southeastern Nigeria." *Journal of Environmental Management*, Vol. 45(2), pp. 234-251.
42. Eze, P.I., & Okoro, M.A. (2022). "Soil Characteristics and Groundwater Vulnerability in the Anambra Basin." *Nigerian Journal of Environmental Sciences*, Vol. 8(3), pp. 112-128.

Industry Guidelines and Associations

43. Liquefied Petroleum Gas Safety Association of Nigeria (LPGSAN). (2023). *Industry Safety Standards for LPG Operations*. Lagos: LPGSAN.
44. Manufacturers Association of Nigeria (MAN). (2023). *Environmental Management Guidelines for Manufacturing Sector*. Lagos: MAN.
45. Nigeria Association of Chambers of Commerce, Industry, Mines and Agriculture (NACCIMA). (2023). *Small Business Environmental Compliance Guide*. Abuja: NACCIMA.

Training and Competency Standards

46. Nigerian Institute of Safety Professionals (NISP). (2024). *LPG Safety Training Curriculum*. Lagos: NISP.
47. NESREA. (2023). *Accredited Environmental Consultant Training Manual*. Abuja: NESREA Training Department.

48. Institute of Environmental Professionals of Nigeria (IEPN). (2023). *Code of Professional Conduct for Environmental Practitioners*. Lagos: IEPN.

49. Council for the Regulation of Engineering in Nigeria (COREN). (2022). *Engineering Practice Standards*. Abuja: COREN.

Emergency Response Resources

50. National Emergency Management Agency (NEMA). (2022). *Industrial Emergency Response Guidelines*. Abuja: NEMA.

51. Federal Fire Service. (2023). *Fire Safety Standards for Petroleum Facilities*. Abuja: Federal Ministry of Interior.

52. International Network for Environmental Compliance and Enforcement (INECE). (2021). *Principles of Environmental Compliance and Enforcement*. Washington DC: INECE.

Community and Social Impact References

53. United Nations Development Programme (UNDP). (2022). *Community Engagement in Environmental Projects: Best Practices*. New York: UNDP.

54. Corporate Social Responsibility Nigeria. (2023). *CSR Guidelines for Oil and Gas Sector*. Lagos: CSR Nigeria.

Audit Methodology References

55. NESREA. (2024). *Environmental Audit Protocol and Checklist (Annexure 2)*. From: National Guidelines for Environmental Audit in Nigeria. Abuja: NESREA.

56. NESREA. (2024). *Format for Environmental Audit Statement - Manufacturing Industries (Annexure 4)*. From: National Guidelines for Environmental Audit in Nigeria. Abuja: NESREA.

Stakeholder Consultation Records

57. Interviews with INNER HOUSE Investment LTD management personnel conducted on September 30, 2025. Unik Concept Consulting Firm.

58. Site observations and photographic documentation compiled by audit team on September 30, 2025. Unik Concept Consulting Firm, Awka.

12. APPENDIX

Photo logs



Figure 1. Back fence with water storage tanks



Figure 2. Picture of the compound and entrance gate



Figure 3. Picture of the alternative power source and administrative block



Figure 4. Picture of the storage tank protective fence



Figure 5. Storage tank with concrete stand support.



Figure 6. Control and utility house



Figure 7. Picture of the 2 nozzles



Figure 8. Picture of the facility entrance from across the road



Figure 9. Picture showing alternate view of the facility



Figure 11.10. Picture of the outside of the fence